

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

DATE: 14.12.2020

3P INSURANCE: NTUC

MODEL: HYUNDAI IONIQ

SURVEYOR: LKK-TAUFIKH

VEH NO.: SHA1228D

MVA: LIM T S

1345.24

301.50

1200.00

2846.74

5 days

PP

1681.55

20%

1345.24

335

10%

301.50

Pasul

4p 90010068

5 days

PIP

14/12/2020 @

1655

Resing Se for paint

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper <i>torn</i>	1		\$459.40 ✓
	Rear Bumper Reinforcement <i>cm</i>	1		\$394.80 ✓
	Rear Bumper Reinforcement Bracket (RH) <i>cut (sting)</i>	1		\$138.10 ✓
	Rear Bumper Centre Moulding Assy <i>cm</i>	1		\$451.25 ✓
	Rear Bumper Lower Centre Moulding Assy <i>sc</i>	1		\$155.00 ✓
	Rear Bumper Side Bracket (RH) <i>? X sc</i>	1		\$55.80
	Rear Bumper Cover Clips <i>sc</i>	10	\$2.20	\$22.00 ✓
	Rear Bumper Under Centre Cover <i>X sc</i>	1		\$225.00
	Rear Bumper Side Under (RH) <i>? X sc</i>	1		\$108.00
	Rear Bumper Tow Cover <i>MIS</i>	1		\$5.40 ✓
	Rear Bumper Reflector Lamp (RH) <i>X sc</i>	1		\$31.90
	Rear Bumper Fog Lamp <i>X sc</i>	1		\$201.50
	Boot Lid <i>repair</i>	1		\$2,480.40
	Emblem-Hybrid <i>sc</i>	1		\$24.30 ✓
	Emblem-Ioniq <i>sc</i>	1		\$31.30 ✓
	Boot Lid Lamp RH <i>X sc</i>	1		\$794.40
				\$5,578.55
	SPARE PARTS SUB TOTAL			\$5,578.55
	LESS 20%			\$1,115.71
	DISCOUNTED SPARE PARTS TOTAL			\$4,462.84
	Boot Lid ComfortDelGro & 65521111 Stickers <i>sc</i>	1		\$60.00 ✓
	Boot Lid Comfort Apps Sticker <i>sc</i>	1		\$40.00 ✓
	Rear Bumper Reverse Sensor <i>AW</i>	1		\$180.00 ✓
	Rear Windscreen Glasses Sealant <i>sc X nn</i>	2	\$46.00	\$92.00 X
	Rear No. Plate W/Trim Cover <i>cm</i>	1		\$55.00 X 55 ✓
				\$427.00
	LESS 10%			\$42.70
	NETT TOTAL			\$384.30
	SPARE PARTS & NETT TOTAL			\$4,847.14
	Panel Beating			\$700.00 640
	Spray Painting			\$500.00
	R/I Reverse Sensor			\$120.00 60
	R/I Both Rear Windscreen Glasses			\$200.00 120 X nn
	Check All Lightings			\$40.00 X nn
	LABOUR TOTAL			\$1,560.00
	ESTIMATE TOTAL			\$6,407.14

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.