



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 1228D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	TORN	459.40	459.40
1	REAR BUMPER REINFORCEMENT	CRACKED	394.80	394.80
1	REAR BUMPER REINFORCEMENT BRACKET (RH)	CUT	138.10	138.10
1	REAR BUMPER CENTRE MOULDING ASSY	CRACKED	451.25	451.25
1	REAR BUMPER LOWER CENTRE MOULDING ASSY	SCRATCHED	155.00	155.00
1	REAR BUMPER SIDE BRACKET (RH)	SERVICEABLE	55.80	-
10	REAR BUMPER COVER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER UNDER CENTRE COVER	SERVICEABLE	225.00	-
1	REAR BUMPER SIDE UNDER (RH)	SERVICEABLE	108.00	-
1	REAR BUMPER TOW COVER	MISSING	5.40	5.40
1	REAR BUMPER REFLECTOR LAMP (RH)	SERVICEABLE	31.90	-
1	REAR BUMPER FOG LAMP	SERVICEABLE	201.50	-
1	BOOT LID	TO REPAIR SEE LABOUR	2,480.40	-
1	EMBLEM - HYBRID	NECESSARY	24.30	24.30
1	EMBLEM - IONIQ	NECESSARY	31.30	31.30
1	BOOT LID LAMP RH	SERVICEABLE	794.40	-
	LESS 20% DISCOUNT		-1,115.71	-336.31
			4,462.84	1,345.24
<u>NETT ITEMS</u>				
1	BOOT LID COMFORTDELGRO & 65521111 STICKERS (N)	NECESSARY	60.00	60.00
1	BOOT LID COMFORT APPS STICKER (N)	NECESSARY	40.00	40.00
1	REAR BUMPER REVERSE SENSOR (N)	NOT WORKING	180.00	180.00
2	REAR WINDSCREEN GLASSES SEALANT @\$46.00 (N)	NOT NECESSARY	92.00	-
1	REAR NO. PLATE W/TRIM COVER (N)	CRACKED	55.00	55.00
	LESS 10% DISCOUNT		-42.70	-33.50
			384.30	301.50

Report Ref No. NS/INC20013819/R1vf3e2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF BOOT LID.		700.00	640.00
	SPRAY PAINTING.		500.00	500.00
	R/I REVERSE SENSOR.		120.00	60.00
	R/I BOTH REAR WINDSCREEN GLASSES.	NOT NECESSARY	200.00	-
	CHECK ALL LIGHTINGS.	NOT NECESSARY	40.00	-
			1,560.00	1,200.00
	GRAND TOTAL		6,407.14	2,846.74
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,846.74

Report Ref No. NS/INC20013819/R1vf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.