



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SBY 77Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TORN	1,045.00	1,045.00
10	FRONT BUMPER CLIP @\$8.00	NECESSARY	80.00	30.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	530.00	-
1	FRONT R/H BUMPER SIDE RETAINER	DAMAGED	28.00	28.00
2	FRONT R/H BUMPER SIDE PARKING SENSOR @\$268.00	DAMAGED (1PC ONLY)	536.00	268.00
1	FRONT R/H BUMPER FOG LAMP	NOT NECESSARY	286.00	-
1	FRONT R/H BUMPER FOG LAMP COVER	NOT NECESSARY	380.00	-
1	FRONT R/H BUMPER FOG LAMP COVER CHROME	CUT	220.00	145.00
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	120.00	-
1	FRONT R/H HEAD LAMP	CRACKED	4,280.00	4,280.00
1	FRONT R/H HEAD LAMP LOWER BRACKET	NOT NECESSARY	355.00	-
1	FRONT BUMPER REINFORCEMENT FOAM (ADDITIONAL)	CRACKED	328.50	125.00
1	FRONT R/H BUMPER INNER HOUSING (ADDITIONAL)	CRACKED	581.20	185.00
	LESS 10% DISCOUNT		-	-610.60
			8,769.70	5,495.40
<u>LABOUR</u>				
	TO REMOVE & REFIT FRONT PARKING SENSOR.		100.00	50.00
	PANEL BEATING.		1,200.00	350.00
	SPRAY PAINTING.		1,000.00	250.00
			2,300.00	650.00
GRAND TOTAL			11,069.70	6,145.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				4,900.00

Report Ref No. CS/INC20013825/Aqd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.