



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: NATALIE LEE		Ref: CS/INC20013825/Aqd3e2 Date: 01/02/2021 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLF 3993R	Veh. Inspected	SBY 77Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1113384-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	14/12/2020
2. Vehicle Particulars & Condition			
Make & Model	B.M.W. 520D	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBAJC32090G580959	Colour	GREY
Odometer	34163 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45 R18	PIRELLI	6 mm
L/H Front Tyre	245/45 R18	PIRELLI	6 mm
R/H Rear Tyre	245/45 R18	PIRELLI	6 mm
L/H Rear Tyre	245/45 R18	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/12/2020	Inspection Date	15/12/2020
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	