



# 新福德車廠私人有限公司

## NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

14/12/2020

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date: 11/12/2020

Estimated repair cost for vehicle no: SBY77Z BMW 520D LED NAV 17'

CHASSIS: WBAJC32090G580959

TP/NC  
Xiao Chen

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bumper <i>torn</i>		\$1,045.00 ✓
2	10	Front Bumper Clip <i>new</i>	\$8.00	\$80.00 30
3	1	Front Bumper Reinforcement <i>new</i>		\$530.00 +
4	1	Front R/H Bumper Side Retainer <i>Damaged</i>		\$28.00 ✓
5	2	Front R/H Bumper Side Parking Sensor <i>1 piece damaged</i>	\$268.00	\$536.00 268
6	1	Front R/H Bumper Fog Lamp <i>new</i>		\$286.00 x
7	1	Front R/H Bumper Fog Lamp Cover <i>new</i>		\$380.00 x
8	1	Front R/H Bumper Fog Lamp Cover Chrome <i>ut</i>		\$220.00 145
9	1	Front Bumper Towing Cover <i>new</i>		\$120.00 x
10	1	Front R/H Head Lamp <i>cracked</i>		\$4,280.00 ✓
11	1	Front R/H Head Lamp Lower Bracket <i>new</i>		\$355.00 x

5796  
5216.40

Subtotal :- \$7,860.00

### Labour charges

To remove & refit front parking sensor

~~\$100.00~~ 50

Panel beating

~~\$1,200.00~~ 350

Spray painting

650  
~~\$1,000.00~~ 250

Subtotal :- \$2,200.00

Total:- \$10,060.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

A.9K

Supplementary 279  
total: 614540  
4/s: 4.9K  
0 Days



# 新福德車廠私人有限公司

## NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

15/12/2020

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date: 11/12/2020

Supplementary repair cost for vehicle no: SBY77Z BMW 520D LED NAV 17'

CHASSIS: WBAJC32090G580959

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bumper Reinforcement Foam <i>Quibid</i>		<del>\$328.50</del> <sup>125</sup>
2	1	Front R/H Bumper Inner Housing <i>Quibid</i>		<del>\$581.20</del> <sup>*</sup>
			Subtotal :-	<u>\$909.70</u> <sup>185</sup>

310

Supplementary: 279.10