



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

15/12/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 11/12/2020

Supplementary repair cost for vehicle no: SBY77Z BMW 520D LED NAV 17'

CHASSIS: WBAJC32090G580959

S/n	Qty	Items / Nett	U/price	Amount
1	1	Front Bumper Reinforcement Foam <i>Quilid</i>		\$328.50 ¹²⁵
2	1	Front R/H Bumper Inner Housing <i>Quilid</i>		\$581.20 [*]
			Subtotal :-	<u>\$909.70</u> ¹⁸⁵

310

Supplementary: 279.10