

Section A - Accident Details

Registration Number	SHD6234L
Case Reference Number	TAX/12/20/2032
Registration Date	13/5/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	PETER TAN
Type of Accident	Side Swipe
Accident Date and Time	11/12/2020 4:30 PM
Accident Reported Date and Time	12/12/2020 10:07 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24109131
Special Instruction to ARC, if any	TP / RIGHT FRONT PORTION
Prepared Date and Time	14/12/2020 8:42 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$1,854.00	\$600.00
Total Spare Part Cost	\$7,015.14	\$1,201.23
Total Other Cost	\$600.00	\$20.00
TOTAL COST	\$10,145.14	\$2,221.23
Lump Sum Total	\$10,150.00	\$2,200.00 (L/S)
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Ang Bang Kien	GUO QIANG (LKK) / AIG
ARC / Surveyor Sign Off Date	14/12/2020 3:57 PM	14/12/2020 3:50 PM
Signature		
Remarks	lump sum repair / after paint photo / FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quogiang (LKK) & Email	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2101-0014	Invoice Number	
Quotation Date	05.01.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
RESPRAY MIRROR COVER RH	\$180.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,854.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE AND REFIX WING MIRROR	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$600.00	\$20.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119-47930	BUMPER FRT	1.00	\$482.00	100.00	\$0.00	Replace	Repair
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52115-47040	BUMPER SUPPORT F/RH	1.00	\$76.40	25.00	\$57.30	Replace	Replace
		52116-47040	BUMPER SUPPORT F/LH	0.00	\$76.40	0.00	\$0.00	Replace	Not Given
		52611-47080	BUMPER ENERGY ABSORBER FRT	0.00	\$78.80	0.00	\$0.00	Replace	Not Given
		52021-47023	BUMPER REINFORCEMENT FRT	0.00	\$498.40	0.00	\$0.00	Replace	Not Given
		57014-47030	ARM SUB-ASSY,FR BUMPER LH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
		57013-47030	ARM SUB-ASSY,FR BUMPER RH	0.00	\$250.40	0.00	\$0.00	Replace	Not Given
			NUMBER PLATE FRAME	0.00	\$12.00	0.00	\$0.00	Replace	Not Given
		52127-47903	COVER, FR BUMPER HOLE RH	0.00	\$18.50	0.00	\$0.00	Replace	Not Given
		53102-47020	BUMPER GRILLE SUB-ASSY,LOWER	0.00	\$311.10	0.00	\$0.00	Replace	Not Given

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 66662623
Accident Reporting Number 66662672

Date Generated : 04/01/2021

User ID kimmingchin

		81210-12230	FOG LAMP RH	0.00	\$295.20	0.00	\$0.00	Replace	Not Given X
		81511-47050	LENS & BODY, FR TURN RH	0.00	\$511.80	0.00	\$0.00	Replace	Check X
		53111-47040	GRILLE, RADIATOR	0.00	\$310.60	0.00	\$0.00	Replace	Not Given X
		53113-47040	GRILLE, RADIATOR LOWER NO.2	0.00	\$94.60	0.00	\$0.00	Replace	Not Given X
		76851-47020	BUMPER LIP FRT	0.00	\$139.60	0.00	\$0.00	Replace	Not Given X
		52618-47050	BUMPER FRT ABSORBER LOWER	0.00	\$127.70	0.00	\$0.00	Replace	Check X
		51410-12105	UNDER COVER CENTER	0.00	\$448.30	0.00	\$0.00	Replace	Not Given X
		53301-47060	HOOD PANEL	1.00	\$748.10	100.00	\$0.00	Replace	Repair X
		53420-47070	HOOD HINRE LH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given X
		53410-47070	HOOD HINGE RH	0.00	\$55.90	0.00	\$0.00	Replace	Not Given X
		81130-47500	HEAD LAMP RH	1.00	\$945.20	10.00	\$850.68	Replace	Replace X
		16533-28051	SUPPORT RADIATOR, RH	1.00	\$54.50	100.00	\$0.00	Replace	Repair X
		53801-47050	FENDER FRT/RH	1.00	\$723.40	25.00	\$542.55	Replace	Replace X
		75374-47051	NAME PLATE (HYBRID)	1.00	\$51.90	25.00	\$38.93	Replace	Replace X
		53827-47030	FENDER PROTECTOR FRT/RH SIDE	0.00	\$113.90	0.00	\$0.00	Replace	Not Given X
		53875-47030	FENDER LINER FRT/RH	0.00	\$171.70	0.00	\$0.00	Replace	Check X
		53851-47040	FENDER LINER PAD, FR WHEEL, RH	0.00	\$49.30	0.00	\$0.00	Replace	Not Given X
		42611-47140	WHEEL DISC, FRONT	0.00	\$1,484.20	0.00	\$0.00	Replace	Not Given X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given X
		75851-47900	MOULDING BODY, RH	1.00	\$673.60	100.00	\$0.00	Replace	Old Damage X
		43550-47011	WHEEL HUB FRT	0.00	\$549.70	0.00	\$0.00	Replace	Not Given X
		87910-47330	MIRROR ASSY, RH	0.00	\$1,307.10	0.00	\$0.00	Replace	Not Given X
		81730-52090	MIRROR LAMP RH	0.00	\$65.30	0.00	\$0.00	Replace	Not Given X
		879157-4010	COVER, OUTER MIRROR, RH	0.00	\$107.40	0.00	\$0.00	Replace	Not Given X
Total					\$11,267.65		\$1,501.54		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1501.54
- 20%
1201.23
+ 400.00
+ 620.00
2221.23
US \$2200/-