

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/III20013830/KGS3Q2**Date:** 06/08/2021REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SHC5834S	Insured Vehicle No :	SHD3505A
Date of Loss:	13/12/2020	Nature of Claim:	TP
		Claim No:	MCT20120241

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5834S	Engine No:	M9R8839C002561
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Chassis No:	VF1ABL15AUC281413
Reg. Date:	06/03/2015 (Man. Year: 2015)	Odometer:	603054 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 8 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 8 mm	Rear Right Side:	Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,758.56	3,708.02	7,050.54	65.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,750.00	1,320.00	3,430.00	72.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,508.56	5,028.02	10,480.54	67.58
Approved Total (Overridden) (S\$)		4,000.00		

	(S\$)	15,508.56	4,000.00	11,508.56	74.21
+ GST 7.00/7.00% (S\$)		1,085.60	280.00	805.60	74.21
Nett Amount (S\$)		16,594.16	4,280.00	12,314.16	74.21
+ Loss of Use (2.0 x S\$40.00/day) (S\$)			80.00		
+ Car Rental (2.0 x S\$95.04/day) (S\$)			190.08		
		Nett Liability (S\$)	4,550.08		

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 15/12/2020

Estimated Period of Repair: 3.0 days

Inspected At:

Trans-Cab Services Pte Ltd (HQ)
2 Ang Mo Kio Street 63
Singapore 569111**Adjuster:** KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 04 Jun 2021)
Parts: 143	RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC5834S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Repair	561.70 FL	*- FL
2	1		*BUMPER LOWER REAR	Serviceable	411.90 FL	*- FL
3	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL
4	1		*BUMPER BEAM BRACKET LH REAR	Serviceable	114.50 FL	*- FL
5	1		*BUMPER BEAM BRACKET RH REAR	Serviceable	114.50 FL	*- FL
6	1		*DOOR PANEL REAR RH	Bent	2,844.66 FL	*2,844.66 FL
7	1		*DOOR REGULATOR REAR RH	Distorted	758.10 FL	*758.10 FL
8	1		*DOOR REGULATOR MOTOR REAR RH	Jammed	450.60 FL	*450.60 FL
9	1		*DOOR CHECK REAR RH	Serviceable	114.90 FL	*- FL
10	1		*DOOR LOCK REAR RH	Repair	467.30 FL	*- FL
11	1		*DOOR HANDLE OUTER REAR RH	Serviceable	42.10 FL	*- FL
12	1		*DOOR HANDLE MODULE REAR RH	Serviceable	133.40 FL	*- FL
13	1		*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- FL
14	1		*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	*- FL
15	1		*TAILLAMP RH	Serviceable	401.40 FL	*- FL
16	1		*ROCKER PANEL OUTER RH	Repair	1,184.99 FL	*- FL
17	1		*SET FENDER SCREW	Not Necessary	60.00 FS	*- FS
18	1		*SET CLIP ,FRONT FENDER LINER	Not Necessary	65.00 FS	*- FS
19	1		*TYRE	Serviceable	300.00 FS	*- FS
20	1		*RIM	Serviceable	350.00 FS	*- FS
21	1		*DOOR FINISHER CLIP KIT REAR RH	Not Necessary	90.00 FS	*- FS
22	1		*DOOR MOULDING CLIP L70Y	Not Necessary	80.00 FS	*- FS
23	1		*DOOR MOULDING SCREW L70Y	Not Necessary	65.00 FS	*- FS
24	1		*DOOR CASING CLIP	Not Necessary	85.00 FS	*- FS
25	1		*REAR DOOR STICKER 6555-3333	Necessary	100.00 FS	*60.00 FS
26	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	*- FS
27	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
28	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	*- FS	
					Sub Total (\$\$)	11,767.85	4,113.36
					- List Item Discount on L Items 10.00/10.00% (\$\$)	1,009.29	405.34
					Total Parts (\$\$)	10,758.56	3,708.02

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEES	New	170.00	0.00
2	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	300.00	60.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
4	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	50.00
6	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	500.00
7	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	660.00
9	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
10	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
			Gross Labour Cost (S\$)	4,750.00
				1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >