

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5834S

AAD2012-

*Not Authorised
L/Sy \$4000/*

Vehicle No.:
Chassis No.:
Vehicle Make: **15 DEC 2020**
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHC5834S
VF1ABL15AUC281413
RENAULT
LATITUDE
13/12/2020
III
06/03/2015

- PART**
- 1 BUMPER COVER REAR
 - 1 BUMPER LOWER REAR
 - 1 BUMPER BEAM REAR
 - 1 BUMPER BEAM BRACKET LH REAR
 - 1 BUMPER BEAM BRACKET RH REAR
 - 1 DOOR PANEL REAR RH
 - 1 DOOR REGULATOR REAR RH
 - 1 DOOR REGULATOR MOTOR REAR RH
 - 1 DOOR CHECK REAR RH
 - 1 DOOR LOCK REAR RH
 - 1 DOOR HANDLE OUTER REAR RH
 - 1 DOOR HANDLE MODULE REAR RH
 - 1 FENDER PANEL REAR RH
 - 1 FENDER BRACKET LOWER RH
 - 1 TAILLAMP RH
 - 1 ROCKER PANEL OUTER RH

LIST

\$	<i>R</i>	561.70	<i>X</i>
\$	<i>Sh</i>	411.90	<i>X</i>
\$	<i>R</i>	547.80	<i>X</i>
\$	<i>Sh</i>	114.50	<i>X</i>
\$	<i>Sh</i>	114.50	<i>X</i>
\$	<i>R</i>	2,844.66	<i>✓</i>
\$	<i>Sh</i>	758.10	<i>—</i>
\$	<i>Sh</i>	450.60	<i>—</i>
\$	<i>Sh</i>	114.90	<i>X</i>
\$	<i>R</i>	467.30	
\$	<i>Sh</i>	42.10	
\$	<i>Sh</i>	133.40	
\$	<i>R</i>	1,933.20	
\$	<i>Sh</i>	11.80	
\$	<i>Sh</i>	401.40	
\$	<i>R</i>	1,184.99	

TOTAL	\$	8,907.86
10%	\$	890.79
	\$	8,017.07

Special Nett

- 1SET FENDER SCREW
- 1SET CLIP, FRONT FENDER LINER
- 1 TYRE
- 1 RIM
- 1 DOOR FINISHER CLIP KIT REAR RH
- 1 DOOR MOULDING CLIP L70Y
- 1 DOOR MOULDING SCREW L70Y
- 1 DOOR CASING CLIP

\$	<i>na</i>	60.00	<i>X</i>
\$	<i>na</i>	65.00	
\$	<i>Sh</i>	300.00	
\$	<i>Sh</i>	350.00	
\$	<i>na</i>	90.00	
\$	<i>na</i>	80.00	
\$	<i>na</i>	65.00	
\$	<i>na</i>	85.00	

Trans-cab Auto Services Pte Ltd

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5834S

1	REAR DOOR STICKER '6555-3333'	\$	<i>na</i>	100.00	<i>60na</i>
2	WINDSCREEN SEALANT	\$	<i>na</i>	150.00	X
1	WINDSCREEN MOULDING	\$	<i>na</i>	200.00	X
1	WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	130.00	X
TOTAL		\$		125.00	

TOTAL PARTS \$ 8,142.07**LABOUR**

Towing fees	\$	<i>na</i>	170.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$		300.00	<i>60a</i>
To check steering geometry and computer wheel alignment	\$	<i>L</i>	220.00	X
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>L</i>	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and others, to enable repair.	\$		380.00	<i>50a</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		1,400.00	<i>500a</i>
To rust-proofing and apply undercoat of the affected areas.	\$		240.00	<i>30a</i>
Putty and spray painting of the affected portion.	\$		1,400.00	<i>660a</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>~</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>20a</i>
TOTAL	\$		4,750.00	