

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5834S**

AAD2012-

*Not Authorised*  
*LIBY \$4000*

Vehicle No.:

Chassis No.:

Vehicle Make:

**15 DEC 2020**

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**SHC5834S**

VF1ABL15AUC281413

RENAULT

LATITUDE

13/12/2020

**III**

06/03/2015

**PART**

**LIST**

- 1 BUMPER COVER REAR
- 1 BUMPER LOWER REAR
- 1 BUMPER BEAM REAR
- 1 BUMPER BEAM BRACKET LH REAR
- 1 BUMPER BEAM BRACKET RH REAR
- 1 DOOR PANEL REAR RH
- 1 DOOR REGULATOR REAR RH
- 1 DOOR REGULATOR MOTOR REAR RH
- 1 DOOR CHECK REAR RH
- 1 DOOR LOCK REAR RH
- 1 DOOR HANDLE OUTER REAR RH
- 1 DOOR HANDLE MODULE REAR RH
- 1 FENDER PANEL REAR RH
- 1 FENDER BRACKET LOWER RH
- 1 TAILLAMP RH
- 1 ROCKER PANEL OUTER RH

\$	<i>n</i>	561.70	<i>X</i>
\$	<i>sn</i>	411.90	<i>X</i>
\$	<i>n</i>	547.80	<i>X</i>
\$	<i>sn</i>	114.50	<i>X</i>
\$	<i>sn</i>	114.50	<i>X</i>
\$	<i>R</i>	2,844.66	<i>✓</i>
\$	<i>DI</i>	758.10	<i>—</i>
\$	<i>sn</i>	450.60	<i>—</i>
\$	<i>sn</i>	114.90	<i>X</i>
\$	<i>n</i>	467.30	
\$	<i>sn</i>	42.10	
\$	<i>sn</i>	133.40	
\$	<i>n</i>	1,933.20	
\$	<i>sn</i>	11.80	
\$	<i>sn</i>	401.40	
\$	<i>n</i>	1,184.99	

<b>TOTAL</b>	\$	<b>8,907.86</b>
<b>10%</b>	\$	<b>890.79</b>
	\$	<b>8,017.07</b>

**Special Nett**

- 1SET FENDER SCREW
- 1SET CLIP, FRONT FENDER LINER
- 1 TYRE
- 1 RIM
- 1 DOOR FINISHER CLIP KIT REAR RH
- 1 DOOR MOULDING CLIP L70Y
- 1 DOOR MOULDING SCREW L70Y
- 1 DOOR CASING CLIP

\$	<i>nn</i>	60.00	<i>X</i>
\$	<i>nn</i>	65.00	
\$	<i>sn</i>	300.00	
\$	<i>sn</i>	350.00	
\$	<i>nn</i>	90.00	
\$	<i>nn</i>	80.00	
\$	<i>nn</i>	65.00	
\$	<i>nn</i>	85.00	

**Trans-cab Auto Services Pte Ltd**

AAD2012-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5834S**

1	REAR DOOR STICKER '6555-3333'	\$	<i>na</i>	100.00	<i>60na</i>
2	WINDSCREEN SEALANT	\$	<i>na</i>	150.00	<i>X</i>
1	WINDSCREEN MOULDING	\$	<i>na</i>	200.00	<i>X</i>
1	WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	130.00	<i>X</i>
<b>TOTAL</b>		<b>\$</b>		<b>125.00</b>	

<b>TOTAL PARTS</b>	<b>\$</b>	<b>8,142.07</b>
--------------------	-----------	-----------------

**LABOUR**

Towing fees	\$	<i>na</i>	170.00	<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$		300.00	<i>60a</i>
To check steering geometry and computer wheel alignment	\$	<i>L</i>	220.00	<i>X</i>
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>L</i>	300.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and others, to enable repair.	\$		380.00	<i>50a</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		1,400.00	<i>500a</i>
To rust-proofing and apply undercoat of the affected areas.	\$		240.00	<i>30a</i>
Putty and spray painting of the affected portion.	\$		1,400.00	<i>660a</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>L</i>	170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>20a</i>
<b>TOTAL</b>	<b>\$</b>		<b>4,750.00</b>	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC5834S**

**AAD2012-**

**Over All Total \$ 12,892.07**

**LUMP SUM (REPAIR DAY)**

~~20 DAYS~~

*3 days*

**For Official Use**

Prepared By : _____ (Accident Dept)
Verify By : _____ (Accident Workshop)
Checked By : _____ (Finance Dept)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: