



AlGAsia Insured's Veh No : GBJ2201Y

Date of Accident : 09 December 2020

Sunpin@lkkauto.com

Sun Pin (LKK)

Messrs Semgas (S) Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following: **TAN LIM MOTOR PTE LTD**

1, Defu Lane 6 Singapore 539365
Tel: 68585151 (24 Hours) Fax: 68580877
GST Regn. No.: M2-8922054-2

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date : 10 December 2020

Acc: LKK
11/12/2020 01220hrs

Estimate To Repair GY3757R - Toyota Dyna 150 (D)

Chassis No : JTFUF34Y603010281

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	tailgate lid / <i>pb</i>	\$ 1,248.00
02	1 pc	tailgate lid Dyna sticker <i>can X</i>	\$ 28.70
03	2 ps	tailgate lid lock handle @ \$102.70 / <i>BT</i>	\$ 205.40
04	2 ps	tailgate lid lock handle bracket @ \$105.00 / <i>BT</i>	\$ 210.00
05	2 ps	tailgate lid rubber stopper @ \$28.40	\$ 56.80
06	2 ps	rear lamp @ \$128.10 / <i>CRA</i>	\$ 256.20
07	2 ps	rear lamp bracket @ \$89.70 / <i>BT</i>	\$ 179.40
08	1 pc	rear licence plate lamp <i>X</i>	\$ 53.60
09	1 pc	rear licence plate bracket / <i>BT</i>	\$ 48.70
10	1 pc	rear exhaust box <i>X</i>	\$ 550.00
11	1 pc	rear end panel <i>X R</i>	\$ 342.70
12	1 pc	rear step U-bar / <i>BT</i>	\$ 150.00
Less 25 %			\$ 3,329.50
			\$ 832.37
			\$ 2,497.12
SPECIAL NETT ITEMS			
13	1 pc	tailgate lid Union sticker / <i>Nec.</i>	\$ 150.00
14	1 pc	tailgate lid 70 KM/H sticker / <i>Nec</i>	\$ 30.00
15	1 pc	rear licence plate / <i>CRA</i>	\$ 80.00
			\$ 260.00
LABOUR & MISC. CHARGES			
01		To check electrical lighting concerned.	\$ 80.00 <i>30</i>
02		To rust-proofing of the affected areas.	\$ 150.00 <i>70</i>
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00 <i>X</i>
04		To drop rear exhaust box and renew the same.	\$ 80.00 <i>X</i>
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00 <i>400</i>
06		Putty and spray painting of the affected portion.	\$ 850.00 <i>600</i>
			\$ 2,180.00
Total			\$ 4,937.13

Repair dly - 3 dlys

After paint photo

11/12/2020

Sun Pin (LKK)

Tan Lim Motor Pte Ltd