



AlGAsia Insured's Veh No : GBJ2201Y
Date of Accident : 09 December 2020

Sunpin@lkkauto.com
Sun Pin (Lkk)

Messrs Semgas (S) Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following: **TAN LIM MOTOR PTE LTD**

1. Defu Lane 6 Singapore 539365
Tel: 68585151 (24 Hours) Fax: 68580877
GST Regn. No. : M2-8922054-2

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date : 10 December 2020

Recy: Lkk
11/12/2020 c1220hrs

Estimate To Repair GY3757R - Toyota Dyna 150 (D)
Chassis No : JTFUF34Y603010281

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	tailgate lid / <i>pd</i>	\$ 1,248.00 ✓
02	1 pc	tailgate lid Dyna sticker <i>scu X NN</i>	\$ 28.70 X
03	2 ps	tailgate lid lock handle @ \$102.70 / <i>BT</i>	\$ 205.40 102.70
04	2 ps	tailgate lid lock handle bracket @ \$105.00 / <i>BT</i>	\$ 210.00 105.00
05	2 ps	tailgate lid rubber stopper @ \$28.40 / <i>Mis.</i>	\$ 56.80 ✓
06	2 ps	rear lamp @ \$128.10 / <i>CRH</i>	\$ 256.20 128.10
07	2 ps	rear lamp bracket @ \$89.70 / <i>BT</i>	\$ 179.40 89.70
08	1 pc	rear licence plate lamp X <i>scu</i>	\$ 53.60 X
09	1 pc	rear licence plate bracket / <i>BT</i>	\$ 48.70 ✓
10	1 pc	rear exhaust box X <i>scu</i>	\$ 550.00 X
11	1 pc	rear end panel X <i>R</i>	\$ 342.70 X
12	1 pc	rear step U-bar / <i>BT</i>	\$ 150.00 120
Less 25 %			\$ 3,329.50 1,899
			\$ 832.37 -25%
			\$ 2,497.12 1,424.25
<u>SPECIAL NETT ITEMS</u>			
13	1 pc	tailgate lid Union sticker / <i>Nec.</i>	\$ 150.00 30
14	1 pc	tailgate lid 70 KM/H sticker / <i>Nec</i>	\$ 30.00 ✓
15	1 pc	rear licence plate / <i>CRH</i>	\$ 80.00 35
			\$ 260.00 95
<u>LABOUR & MISC. CHARGES</u>			
01		To check electrical lighting concerned.	\$ 80.00 30
02		To rust-proofing of the affected areas.	\$ 150.00 70
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 120.00 X
04		To drop rear exhaust box and renew the same.	\$ 80.00 X
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 900.00 400
06		Putty and spray painting of the affected portion.	\$ 850.00 400
			\$ 2,180.00 860
Repair dy - 3 dlys Total 415 After paint photo 11/12/2020. Sun Pin (Lkk) TP...			1,424.25 95 860 2,379.25 -20% 1,903.45
			\$ 4,937.13
			415 \$1,900 3dlys