



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 242A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BONNET	BENT	3,708.96	2,573.96
2	FRONT BONNET HINGES (LH/RH)	TO REPAIR SEE LABOUR	756.02	-
1	FRONT BONNET CENTER RUBBER	SERVICEABLE	42.57	-
2	FRONT BONNET RUBBER (LH/RH)	SERVICEABLE	85.14	-
1	RHF FENDER	BENT	1,583.81	1,453.22
1	RHF FENDER TOP SHIELD	SERVICEABLE	239.57	-
1	RHF FENDER LOWER SHIELD	SERVICEABLE	72.03	-
1	RHF FENDER TOP PANEL	SERVICEABLE	1,419.33	-
1	RHF FENDER END BRACKET	TO REPAIR SEE LABOUR	49.12	-
1	RHF FENDER TOP BRACKET (FRONT)	TO REPAIR SEE LABOUR	98.23	-
1	RHF FENDER TOP BRACKET (MID)	SERVICEABLE	65.49	-
1	RHF FENDER TOP BRACKET (REAR)	TO REPAIR SEE LABOUR	29.47	-
1	RHF HEADLAMP	CRACKED	8,358.84	7,186.65
1	SET RHF HEADLAMP BRACKET	SERVICEABLE	139.10	-
1	RHF BUMPER BRACKET (ADDITIONAL)	CRACKED	64.57	64.57
1	RHF SIDE FENDER EMBLEM (ADDITIONAL)	NECESSARY	233.69	233.69
	LESS 5% DISCOUNT		-847.30	-575.60
			16,098.64	10,936.49
<u>SPECIAL NETT ITEMS</u>				
2	FRONT RIMS (LH/RH)(SN)	SERVICEABLE	1,600.00	-
2	NITROGEN GAS FOR TYRE PRESSURE (SN)	SERVICEABLE	280.00	-
			1,880.00	-
<u>LABOUR</u>				
	TO CHECK LIGHTINGS & WIRINGS.		380.00	20.00
	PROGRAMMING AND CALIBRATION RESET.		280.00	120.00

Report Ref No. CS/SMO20013834/Ktf3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO DISMANTLE,REPAIR,REPLACE AND ALIGN THE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGES (LH/RH) ,RHF FENDER END BRACKET,RHF FENDER TOP BRACKET (FRONT) AND RHF FENDER TOP BRACKET (REAR).	NOT NECESSARY	1,000.00	450.00
	LABOUR TO REMOVE AND REINSTALL TPMS (TYRE PRESSURE MONITORING SYSTEM) FROM OLD RIMS TO NEW RIMS.		200.00	-
	TO PUTTY,PRIMER,SPRAY PAINT FRONT BONNET,RHR FENDER.		1,200.00	480.00
	WHEEL ALIGNMENT AND HIGH SPEED BALANCING.		280.00	60.00
			3,340.00	1,130.00
GRAND TOTAL			21,318.64	12,066.49
RECOMMENDED COST OF REPAIRS				12,066.49

Report Ref No. CS/SMO20013834/Ktf3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.