



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO20013834/Ktf3q2	
			Date: 25/02/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 4390G	Veh. Inspected	SMQ 242A
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2003654/THE	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	15/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A5 (A)	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WAUZZZF55KA071001	Colour	RED
	Odometer	12341 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/30 ZR20	PIRELLI	8 mm
	L/H Front Tyre	275/30 ZR20	PIRELLI	8 mm
	R/H Rear Tyre	275/30 ZR20	PIRELLI	8 mm
	L/H Rear Tyre	275/30 ZR20	PIRELLI	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/12/2020	Inspection Date	28/12/2020
	Survey held at	CHUAN HO AUTO SERVICE BLK 11 SECTOR B #01-85 SIN MING IND ESTATE SINGAPORE 575656.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	