

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 14 December 2020

To : LKK

Attn : Bryan

By Fax: 6256-4315

Tel: 97237799

VEHICLE NO : FL 5440X

Yamaha R3

ACCIDENT DATE: 9 December 2020

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Clutch Lever <i>broken</i>	1	90.00 ✓
2 Balancer <i>1/3 1/4</i>	1 set	250.00 ✓ 125.00
3 Tail Tidy <i>distorted / damaged</i>	1	220.00 ✓
4 Brake Lever <i>new</i>	1	120.00 X
5 Left Side Lower Fairing <i>new</i>	1	290.00 ✓
6 Tail Panel <i>new</i>	1	280.00 ✓
7 Handle Bar LH <i>1/4 new</i>	1	160.00 <i>new</i> X
8 Front Side Centre Panel (Fairing) <i>new</i>	1	320.00 ✓
9 Fork Tube <i>new</i>	1 set	1,800.00 X
10 Clutch Switch <i>broken</i>	1	265.00 ✓

Sub-Total 3,795.00

Less 10% 379.50

Sub-Total 3,415.50

1590.00

107. 1431.00

VEHICLE NO : FL 5440X

Yamaha R3

Nett Items

- 1 Sticker decal set *new*
- 2 Number plate *new*
- 3 Re-spray paint
- 4 Labour to replace above parts, align
& etc & replace fork tube, top up
fork oil.

280.00

90.00 50/-
15.00 x
~~800.00~~ 150/-
280.00 80/-

Sub-Total

1,185.00

Nett Total

4,600.50

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

S9 MOTOR TRADING PTE LTD

:LG

1711.00

L/S 1350/-

14/12/2020 @ 1800hrs

Not Antenna

L/S new

3 days

LKK Antenna

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: