



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102766

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 20/04/2021
Reference CC4/FCI20013848/R1ra3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. XE 739S
Insured Veh. SHB 2996H
Claim No. D20005102MFSH/1
Policy No. D-20094921MFSH
Accident Date 14/12/2020
Inspection Date 15/12/2020

Description	Total
Survey Inspection	416.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	416.00
GST (7%)	29.12
Grand Total	445.12

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20013848/R1ra3q2	
			Date: 20/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 2996H	Veh. Inspected	XE 739S
	Policy No.	D-20094921MFSH	Coverage (\$)	0.00
	Claim No.	D20005102MFSH/1	Excess (\$)	0.00
	Assign From	ERIC WOO	Assign Date	15/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	IVECO TRAKKER AUTO	c.c	12882
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WJME2NSS40C281171	Colour	WHITE
	Odometer	305366 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	385/65 R22.5	MIRAGE	8 mm
	L/H Front Tyre	385/65 R22.5	MIRAGE	8 mm
	R/H Rear Tyre	385/65 R22.5 (D)	MIRAGE	8/8 mm
	L/H Rear Tyre	385/65 R22.5 (D)	MIRAGE	8/8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/12/2020	Inspection Date	15/12/2020
	Survey held at	VFIX AUTO SERVICE PTE LTD 26 CHIA PING ROAD SINGAPORE 619977		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 739S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	NOT NECESSARY	1,965.00	-
1	SIDE BUMPER LH	TO REPAIR SEE LABOUR	1,856.00	-
1	FRONT HEADLAMP LH	NOT NECESSARY	1,105.00	-
1	FRONT HEADLAMP LH BRACKET	NOT NECESSARY	865.00	-
1	FRONT BUMPER LAMP LH (NOT NECESSARY)	OLD DAMAGED	480.00	-
1	FRONT BUMPER SIDE LAMP LH	CRACKED	420.00	92.00
1	STEP BOARD UPPER LH	NOT NECESSARY	1,796.50	-
1	STEP BOARD LOWER LH	CRACKED	1,216.90	722.00
1	STEP BOARD CENTER LH	CUT	1,696.50	485.00
1	STEP BOARD BRACKET	NOT NECESSARY	895.00	-
	LESS 10% DISCOUNT		-	-129.90
			12,295.90	1,169.10
	<u>SPECIAL NETT ITEMS</u>			
1	BODY SEALANT (SN)	NOT NECESSARY	60.00	-
			60.00	-
	<u>LABOUR</u>			
	TO REMOVE DAMAGED BODY PANEL WITH ALL NECESSARY COMPONENTS /ATTACHMENTS APPLY HOT-WORKS WHERE NECESSARY STRAIGHTEN FRONT DOOR PILLAR ,REPAIR /RESHAPE BODY DENTED PANELS IN ACCORDANCE WITH FACTORY SPECIFICATIONS REPLACE NEW PARTS REFIT AND ALIGN INTO POSITION REFIT ALL NECESSARY COMPONENTS /ATTACHMENTS .INCLUSIVE OF THE REPAIR OF SIDE BUMPER LH .		2,000.00	300.00
	TO SPRAY PAINT REPLACED/REPAIRED BODY PANELS INCLUSIVE OF PREPARATORY WORKS AND PAINTING MATERIALS .		2,000.00	200.00
	CHECK AND RECONNECT WIRING SYSTEM.		120.00	30.00
			4,120.00	530.00
	GRAND TOTAL		16,475.90	1,699.10



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,350.00
---	--	--	-----------------

Report Ref No. CC4/FCI20013848/R1ra3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 739S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. XE 739S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

