



Vfix Auto Pte Ltd
26 Chia Ping Road
Singapore 619977
Email: contact@vfixauto.com.sg
Tel: 64552957 Fax: 68628669
UEN / GST REG No.: 201830761R

ESTIMATE

Attention: Motor Claim Department

DATE
SHEET NO. 1 OF 1 SHEET

14/12/2020

RE: VEHICLE NO: XE789S IVECO TRAKKER (HOCK LIAN SENG INFRASTRUCTURE PTE LTD)

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	1	FRONT BUMPER LN NN		1,965.00 X
2	1	SIDE BUMPER LH repair		1856.00 XR
3	1	FRONT HEADLAMP LH LN	1299	1105.00 X
4	1	FRONT HEADLAMP LH BRACKET LN		865.00 X
5	1	FRONT BUMPER LAMP LH old damage LN	10%	480.00 ✓
6	1	FRONT BUMPER SIDE LAMP LH LN		420.00 92
7	1	STEP BOARD UPPER LH LN	1169.10	1796.50 X
8	1	STEP BOARD LOWER LH LN		1216.90 722
9	1	STEP BOARD CENTER LH LN		1696.50 485
10	1	STEP BOARD BRACKET LN		895.00 X
				\$ 12,295.90

S/NO.	QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$
1	1	SPECIAL NET		
1	1	Body Sealant LN		\$ 60.00
				\$ 60.00 X

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S\$
1	1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	2,000.00 300
2	1	To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	2,000.00 200
3	1	Check and reconnect wiring system	120.00 30
GRAND TOTAL :			\$ 4,120.00
			\$ 16,475.90

ISSUED BY

WENG SHENG

KOH WENG SHENG

ESTIMATE CONFIRMED AND ACCEPTED BY

NAME, SIGNATURE, DATE SIGNED

1169.10

530.00

1699.10

20%

1359.28

4/5-1,350

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
Hp 90010068

3 days

4/5

15/12/2020 @ 1620

Resy after repair