

MBM WHEELPOWER PTE. LTD.

REF.: GX3831P
REF.: SMR4877L

CHINA TAIPING

MOTOR CLAIMS DEPARTMENT

*Not Authorized
11 Sep 83800h
Primary After Point
4 days*



DATE: 14/1/2021
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: MERCEDES BENZ C180 AVANTGARDE
CHASSIS NO.: WDD2050402R026397
ENGINE NO.: 27491030287981
YEAR MADE: 2015
ACCIDENT DATE: 3 December 2020

ESTIMATE FOR VEHICLE NO.: SMR4877L

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BOOTLID <i>2248.00</i>		1	\$ <i>✓</i> <i>22</i> 2,400.00 <i>✓</i>
2	BOOTLID WEATHERSTRIP		1	\$ <i>X</i> <i>22</i> 225.00
3	BOOTLID HINGE LH		1	\$ <i>X</i> <i>22</i> 290.00
4	BOOTLID HINGE RH		1	\$ <i>22</i> <i>X</i> 290.00
5	BOOTLID LOCK		1	\$ <i>22</i> <i>X</i> 332.00
6	BOOT LID MERCEDES LOGO		1	\$ <i>22</i> <i>✓</i> 54.00
7	BOOTLID "C180" EMBLEM		1	\$ <i>22</i> <i>✓</i> 96.00
9	BOOTLID CHROME STRIP		1	\$ <i>22</i> <i>✓</i> 140.00 <i>✓</i>
10	TAIL LAMP LH		1	\$ <i>22</i> <i>X</i> 720.00
11	TAIL LAMP RH		1	\$ <i>22</i> <i>X</i> 720.00
12	REAR BUMPER <i>1590</i>		1	\$ <i>22</i> <i>✓</i> 1,800.00
14	REAR BUMPER RETAINER LH		1	\$ <i>22</i> <i>X</i> 75.00
15	REAR BUMPER RETAINER RH		1	\$ <i>22</i> <i>X</i> 75.00
16	REAR BUMPER REINFORCEMENT		1	\$ <i>22</i> <i>✓</i> 700.00 <i>X</i>
17	REAR BUMPER SENSOR		1	\$ <i>22</i> <i>✓</i> 200.00 <i>X</i>
18	REAR BUMPER CLIP		10	\$ <i>22</i> <i>✓</i> 80.00
19	REAR BUMPER LOWER SPOILER		1	\$ <i>22</i> <i>X</i> 240.00
20	REAR BUMPER LOWER SPOILER CHROME TRIM		1	\$ <i>22</i> <i>X</i> 270.00
TOTAL:				\$ 8,707.00
LESS 10%:				\$ (870.70)
PARTS TOTAL:				\$ 7,836.30

SPECIAL NETT

REAR NUMBER PLATE & HOLDER
BODY SEALANT ON BOOTLID

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #08-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS

\$ 400 1,200.00

TO CHECK & RECONNECT ALL NECESSARY WIRING

\$ 20 100.00

TO REMOVE & REFIT ALL SENSOR

\$ 60 100.00

TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)

\$ MAX 150.00 X

TO SPRAY PAINT ON THE AFFECTED AREAS

\$ 500 1,200.00

TOTAL: \$ 10,686.30

7% GST: \$ 748.04

GRAND TOTAL: \$ 11,434.34

MBM WHEELPOWER PTE. LTD.

160 SIN MING DRIVE, #06-02

SIN MING AUTOCITY

t 6262 8888 f 6452 5333

COMPANY REG. NO.: 200204110W