

ASS. REC. BY:

REF:

CCA/FCI200130851/APS?

OK

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLU5066A Yr Regn: 2017, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius Alpha Hybrid c.c 1797

Colour: silvers A/C: Insured / Std / NI / NA

Sp. Reading: 211022 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZVWA100071234 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Harbiled

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 15/12/20

Survey held at NSI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to? : **Preli. Report**

1) : **Final Report**

Date/Time, File Return to?

2) _____

Report Format : _____

Lump Sum / L.R. : (C) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + RS. _____ \$

Photos _____

Others _____

TOTAL _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

13887 / Ae

TP 1st Cap.

Asher.

DARWIN-51 CAR RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

ESTIMATE

Repair Code : CLM16592

Date in : 11/12/2020

Vehicle Num. : SLU5066A

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400027234/2ZR0A26951

Contact : 87920654

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Disbled</i>	1	781.10	✓ 781.10
FRONT BUMPER AIR GARNISH LH <i>could</i>	1	98.70	✓ 98.70
FRONT BUMPER DAY LAMP LH <i>could</i>	1	972.85	766 ✓ 972.85
FRONT BUMPER LH FOGLAMP <i>could</i>	1	591.60	296 ✓ 591.60
FRONT BUMPER LOWER GRILLE <i>Disbled</i>	1	563.30	✓ 563.30
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	681.90	✓ 681.90
FRONT BUMPER SIDE BRACKET LH <i>could</i>	1	171.10	✓ 171.10
FRONT BUMPER SIDE RETAINER L/R <i>LH could</i>	2	132.25	132.25 264.50
FRONT BUMPER SPONGE <i>could</i>	1	174.45	✓ 174.45
FRONT BUMPER TOP RUBBER SEAL <i>not in</i>	1	174.45	+ 174.45
FRONT BUMPER TOW HOOK COVER L/R <i>LH Disbled</i>	2	121.45	121.45 242.90
FRONT BUMPER UNDER COVER <i>tone</i>	1	139.50	✓ 139.50
FRONT GRILLE <i>could</i>	1	395.00	✓ 395.00
FRONT GRILLE 'LOGO' EMBLEM <i>in</i>	1	108.00	✓ 108.00
FRONT GRILLE TOP GARNISH <i>not in</i>	1	169.00	+ 169.00
FRONT HEADLAMP L/R <i>LH could</i>	2	2721.10	2721.10 5442.20
FRONT HEADLAMP LOWER BRACKET L/R <i>not in</i>	2	55.00	+ 110.00
FRONT LH FENDER <i>Disbled</i>	1	731.35	✓ 731.35

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 87920654

ESTIMATE

Repair Code : CLM16592

Date in : 11/12/2020

Vehicle Num. : SLU5066A

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400027234/2ZR0A26951

FRONT LH FENDER 'HYBRID' EMBLEM <i>neu</i>	1	123.05	✓	123.05
FRONT LH FENDER INNER BRACKET <i>Best</i>	1	26.00	✓	26.00
FRONT LH FENDER INNER PANEL <i>Rp</i>	1	268.00	+	268.00
FRONT LH FENDER INNER SHIELD (VERTICAL) <i>form</i>	1	259.45	✓	259.45
FRONT LH KNUCKLE ARM <i>Best</i>	1	485.00	✓	485.00
FRONT LH KNUCKLE ARM BEARING <i>neu</i>	1	502.00	✓	502.00
FRONT LH LOWER ARM <i>Best</i>	1	435.00	✓	435.00
FRONT LH SHOCK ABSORBER <i>neu</i>	1	375.00	+	375.00
FRONT LH SHOCK ABSORBER TOP MOUNTING <i>neu</i>	1	151.00	+	151.00
FRONT LH SPORT RIM <i>ct</i>	1	1555.00	750(SW) ✓	1,555.00
FRONT LH STABILIZER LINK <i>neu</i>	1	117.00	+	117.00
FRONT LH TIE ROD END <i>neu</i>	1	93.00	+	93.00
FRONT LH WHEEL HUB CAP <i>neu</i>	1	114.00	+	114.00
FRONT SUPPORT PANEL <i>Rp</i>	1	972.75	+	972.75
Subtotal before discount				17,288.15
Percentage discount 25%				4,322.04
Sub-total 1				12,966.11
FRONT BUMPER CLIPS - SET <i>neu</i>	1	50.00	✓	50.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 87920654

ESTIMATE

Repair Code : CLM16592
 Date in : 11/12/2020
 Vehicle Num. : SLU5066A
 Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT
 Chassis/Eng# : ZVW400027234/2ZR0A26951

FRONT GRILLE CLIPS - SET <i>Nlu</i>	1	30.00	✓	30.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>nu</i>	1	50.00	30	50.00
RADIATOR COOLANT <i>no nu</i>	1	80.00	X	80.00
Subtotal before discount				210.00
Percentage discount 0%				0.00
Sub-total 2				210.00
Parts-total				13,176.11

LABOUR

To remove, reinstall air con parts, vacuums, refill air con gas. (to FR)	X	120.00
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	30	80.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	180	280.00
To road test driving, check and resetting wheel alignments system.	80	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	800	1,400.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	600	1,000.00
To apply anti-rust chemical on repaired and replaced panel.	40	80.00
Labour Total		3,060.00
Parts & Labour Total		16,236.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

page 3

total: 985377
 H/S: 7.8K ✓
 Admin Lj
 H/s 15/12/20.
 05 Days.

*** This is a computer-generated document which requires no signature.***