



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2100333

INV Date 15/01/2021

Reference CC4/LPC20013853/Kps3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLE 1036Y
Insured Veh. SLV 8727B
Claim No. 20/20/20/VP00/023980
Policy No. Z/20/VP00/10536
Accident Date 06/12/2020
Inspection Date 16/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20013853/Kps3q2 Date: 15/01/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLV 8727B	Veh. Inspected	SLE 1036Y	
Policy No.	Z/20/VP00/10536	Coverage (\$)	0.00	
Claim No.	20/20/20/VP00/023980	Excess (\$)	0.00	
Assign From	KENNY	Assign Date	15/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLC250 (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	WDC2539462F058518	Colour	METALLIC BLACK	
Odometer	41335 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/60 R18	PIRELLI	8 mm	
L/H Front Tyre	235/60 R18	PIRELLI	8 mm	
R/H Rear Tyre	235/60 R18	PIRELLI	8 mm	
L/H Rear Tyre	235/60 R18	PIRELLI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/12/2020	Inspection Date	16/12/2020	
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 1036Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR -LH (N)	BENT	2,696.00	2,696.00
1	FRONT DOOR WEATHERSTRIP -LH (N)	NECESSARY	328.00	328.00
1	REAR DOOR -LH (N)	BENT	2,925.00	2,925.00
1	REAR DOOR WEATHERSTRIP -LH (N)	NECESSARY	328.00	328.00
	LESS 10% DISCOUNT		-627.70	-627.70
			5,649.30	5,649.30
20	FRONT DOOR TRIMBOARD RIVETS -LH @\$13.00 (SN)	NECESSARY	260.00	60.00
20	REAR DOOR TRIMBOARD RIVET -LH @\$13.00 (SN)	NECESSARY	260.00	60.00
	LESS 10% DISCOUNT		-52.00	-
			468.00	120.00
	<u>LABOUR</u>			
	TO TRANSFER LH FRONT AND REAR DAMAGED DOOR INTERIOR MECHANISM AND GLASS TO NEW DOOR .		300.00	120.00
	TO PANEL BEAT AND STRAIGHTEN LH FRONT & REAR DOOR HINGES ,INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY ,TO REFIT AND ADJUST THE SAME.		800.00	400.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	20.00
	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.		800.00	500.00
	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS.	NOT NECESSARY	120.00	-
			2,100.00	1,040.00
GRAND TOTAL			8,217.30	6,809.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,400.00

Report Ref No. CC4/LPC20013853/Kps3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 1036Y

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLE 1036Y

RE-INSPECTION

