AUTHORISATION LETTER

I, DAIMLER FLEET MANAGEMENT S'PORE PTE LTD of 1 GATEWAY DRIVE #15-08
WESTGATE TOWER SINGAPORE 608531, owner of SLE1036Y hereby authorize TONG
LUCK AUTO PTE LTD to act for me with my respect to our claim for repair costs and/or
rental and/or loss of use for our vehicle no.: SLE1036Y that was damaged pursuant to the
accident which occurred on 06/12/2020 ALONG WHEELOCK PLACE OPEN SPACE
CARPARK involving vehicle nos: SLV8727B

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the

Dated this 14th day of December 2020

Po Co

kashini

Signed by third party claimant

TONG LUCK AUTO PTE LTD



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Website: www.tlauto.com.sg Email: operation@tlauto.com.sg

UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER SINGAPORE 608531

TEL: 6849 8118 FAX:

YOUR REF NO : 20/20/20/VP00//023980

CLAIM TYPE : THIRD PARTY ACCIDENT DATE: 06/12/2020

TP VEHICLE NO : SLV8727B

: AR202012-0061 NO

CLAIM NO : QUOT202012-000053(01)

DATE : 22/12/2020 POLICY NO : 999995580 **VEH REG** : SLE1036Y

MAKE/MODEL: MERCEDES BENZ GLC250

4MATIC (R18 LED) : WDC2539462F058518

CHASIS NO ENGINE NO : 27492030499549

: 2016 REG. DATE

Final Repair Cost to Vehicle No: SLE1036Y

	Description	Quantity	Unit Price	Amount
			<u>ss</u>	<u> </u>
	NET PRICE			
1	Front door - LH	1	2,696.00	2,696.00
2	Front door weatherstrip - LH	1	328.00	328.00
3	Rear door-LH	1	2,925.00	2,925.00
4	Rear door weatherstrip - LH	1	328,00	328.00
			-	6,277.00
			Less 10%	627.70
			-	5,649.30
	SPECIAL NET			
5	Front door trimboard rivets - LH (set)	1	60.00	60,00
6	Rear door trimboard rivet - LH (set)	1	60.00	60.00
			•	120.00
	LABOUR			
8	To transfer LH front and rear damaged door interior mechanism	1	120.00	120.00
9	and glass to new door To panel beat and striaghten LH front & rear door hinges, including replacement of parts and align where necessary, to refit and adjust the same	1	400.00	400.00
10	To check and rectify wiring system	1	20.00	20.00
11		1	500.00	500.00
				1,040.00

AMOUNT: \$\$6,809.30

LUMP SUM DISCOUNT: \$\$ -1,409.30

> TOTAL: \$\$5,400.00

S\$378.00 ADD GST @ 7%:

\$\$5,778.00 **GRAND TOTAL:**

SINGAPORE DOLLARS FIVE THOUSAND SEVEN HUNDRED AND SEVENTY-EIGHT AND CENTS ZERO ONLY



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Website: www.tlauto.com.sg

Email: operation@tlauto.com.sg UEN: 201700521W GST NO.: 201700521W

TAX INVOICE

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD (TP)

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER

SINGAPORE 608531

TEL: 6849 8118

FAX:

YOUR REF NO : 20/20/20/VP00//023980

CLAIM TYPE

: THIRD PARTY

ACCIDENT DATE: 06/12/2020

TP VEHICLE NO : SLV8727B

Description

NO

: AR202012-0061

CLAIM NO

: QUOT202012-000053(01)

DATE

: 22/12/2020

POLICY NO

: 999995580

VEH REG

: SLE1036Y

MAKE/MODEL: MERCEDES BENZ GLC250

4MATIC (R18 LED)

CHASIS NO

: WDC2539462F058518

ENGINE NO

: 27492030499549

REG. DATE

: 2016

Final Repair Cost to Vehicle No: SLE1036Y

Quantity

Unit Price

Amount

SS

SS

TONG LUCK AUTO PTE LTD

E. & O.E.

AUTHORISED SIGNATURE

> Back to OneMotoring



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

14 Dec 2020 / 11:47:44

Receipt Date/Time: 14 Dec 2020 / 11:47:44

Tax Invoice/Receipt

Receipt No.: ITNET-00000-201214-001515

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLV8727B As at 06 Dec 2020/16:22:00 Insurance Co: LONPAC INSURANCE BHD 1 Insurance Enquiry - SLV8727B				
Enquiry Fee 20201214114549428565		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	518834XXXXXX2002	eNETS Credit Car	rd	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire Vehicle's Insurance Particulars

Thank You!

The insurance details of the vehicle you enquired can be found below. If you have entered a valid email address, a copy would have been sent to you.

Vehicle No. SLV8727B	Incident Date/Time 06 Dec 2020 / 16:22:00	Insurance Company Name LONPAC INSURANCE BHD
Save as PDF		OK →
Print		

1



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

Our Ref

: SLE1036Y

Yours Ref

: 20/20/20/VP00//023980

LONPAC INSURANCE BHD

22 December 2020

300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555

Attn: MOTOR CLAIMS DEPT

Dear Sir / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SLE1036Y & SLV8727B ON 06/12/2020 @ 16:22 HRS ALONG WHEELOCK PLACE OPEN SPACE CARPARK

The vehicle had been surveyed by your appointed surveyor and repaired to our client's satisfaction.

We hereby submit the details of claim as follow:

Cost of Repair

S\$5,778.00

Loss of Use (\$ 150.00 x 4 days)

S\$600.00

Additional Loss of Use (\$ 150.00 x 1 days) - Weekend

S\$150.00

GIA / LTA Search

S\$7.45

S\$6.535.45

Kindly revert within SEVEN days. Filling which we reverse our rights to refer the matter to our solicitors.

Your kind attention to the matter would be much appreciated.

Yours faithfully

TONG LUCK AUTO RIE LTD