



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118 FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : SLV8727B

CLAIM TYPE : THIRD PARTY

TP INS. CO. : LONPAC INSURANCE BHD

ACCIDENT DATE : 06/12/2020

TP VEH REG NO : SLV8727B

## ESTIMATE

NO : QUOT202012-000053(00)

DATE : 14/12/2020

POLICY NO : 999995580

VEH REG NO : SLE1036Y

MAKE/MODEL : MERCEDES BENZ GLC250  
4MATIC (R18 LED)

CHASSIS NO : WDC2539462F058518

ENGINE NO : 27492030499549

REG. DATE : 2016

### Estimate Repair Cost to Vehicle No : SLE1036Y

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
<b>NET PRICE</b>			
1 Front door - LH	1	2,696.00	2,696.00
2 Front door weatherstrip - LH	1	328.00	328.00
3 Front door trimboard rivets - LH	20	13.00	260.00
4 Rear door - LH	1	2,925.00	2,925.00
5 Rear door weatherstrip - LH	1	328.00	328.00
6 Rear door trimboard rivet - LH	20	13.00	260.00
			6,797.00
		Less 10%	679.70
			6,117.30
<b>LABOUR</b>			
7 To transfer LH front and rear damaged door interior mechanism and glass to new door	1	300.00	300.00
8 To panel beat and straighten LH front & rear door hinges, including replacement of parts and align where necessary, to refit and adjust the same	1	800.00	800.00
9 To check and rectify wiring system	1	80.00	80.00
10 To putty and spray paint on affected areas	1	800.00	800.00
11 To apply rust-proofing on replaced and repaired panels	1	120.00	120.00
			2,100.00
TOTAL			<b>S\$ 8,217.30</b>
ADD GST @ 7%			575.21
GRAND TOTAL			<b>S\$ 8,792.51</b>

SINGAPORE DOLLAR EIGHT THOUSAND SEVEN HUNDRED NINETY-TWO AND CENTS FIFTY-ONE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



## TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

LONPAC INSURANCE BHD  
300 BEACH ROAD #17-04/07  
THE CONCOURSE  
SINGAPORE 199555

14 December 2020

Attn: MOTOR CLAIMS DEPT

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: SLE1036Y & SLV8727B ON 06/12/2020 @ 16:22 HRS ALONG  
WHEELLOCK PLACE OPEN SPACE CARPARK

We hereby authorized by our client **DAIMLER FLEET MANAGEMENT S'PORE PTE LTD**, the owner/driver  
of the above mentioned vehicle No.: **SLE1036Y**

We notice that the above accident was caused by your insured/driver negligent driving and/or management  
of motor vehicle No.: **SLV8727B**

Therefore we are instructed by our client to claim against you/your insured driver in connection with the  
above captioned accident involving our client's vehicle No.: **SLE1036Y** and vehicle No.: **SLV8727B** by your  
insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put  
to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs.  
Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at: **TONG LUCK AUTO PTE LTD**  
160 Sin Ming Drive  
#07-01/06 Sin Ming Autocity  
Singapore 575722  
Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD