

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI20013855/KVD3E2

Date: 22/12/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MS004226

Claimant Vehicle No : SHD11C

Insured Vehicle No : SMK6509Z

Date of Loss: 11/12/2020

Nature of Claim: TP

Claim No: M2006134

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD11C**

Make & Model: RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR (A)

Engine No: M9R8839C003019

Reg. Date: 31/05/2016 (Man. Year: 2015)

Chassis No: VF1ABL15AUC282636

Colour: Metallic White/Red

Odometer: 467397 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Sailun 8 mm

Rear Left Side: Sailun 8 mm

Front Right Side: Sailun 8 mm

Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,699.49	3,200.72	12,498.77	79.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	1,490.00	2,790.00	65.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	19,979.49	4,690.72	15,288.77	76.52
Approved Total (Overridden) (\$\$)		3,750.00		
(\$\$)	19,979.49	3,750.00	16,229.49	81.23
+ GST 7.00/7.00% (\$\$)	1,398.56	262.50	1,136.06	81.23
Nett Amount (\$\$)	21,378.05	4,012.50	17,365.55	81.23

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 14/12/2020

Inspected At:

Trans-Cab Services Pte Ltd (HQ)

2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Dec 2020)

Parts: 143 RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD11C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*DOOR MIRROR LH	Serviceable	1,483.40 FL	-	*- FL
2	1		*DOOR PANEL REAR LH	Bent / Warped	2,844.66 FL	-	*2,844.66 FL
3	1		*DOOR REGULATOR REAR LH	Serviceable	450.60 FL	-	*- FL
4	1		*DOOR REGULATOR MOTOR REAR LH	Serviceable	758.10 FL	-	*- FL
5	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	311.60 FL	-	*- FL
6	1		*DOOR PANEL FRT LH	Repair	2,844.66 FL	-	*- FL
7	1		*DOOR HANDLE OUTER FRT LH	Serviceable	169.50 FL	-	*- FL
8	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.40 FL	-	*- FL
9	1		*DOOR GRAB HANDLE FRT LH	Serviceable	146.90 FL	-	*- FL
10	1		*DOOR REGULATOR FRT LH	Serviceable	501.40 FL	-	*- FL
11	1		*DOOR REGULATOR MOTOR FRT LH	Serviceable	758.10 FL	-	*- FL
12	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	69.00 FL	-	*- FL
13	1		*DOOR WEATHERSTRIP FRT LH	Serviceable	316.00 FL	-	*- FL
14	1		*DOOR LOCK FRT LH	Repair	453.80 FL	-	*- FL
15	1		*ROCKER PANEL OUTER LH	Repair	1,184.99 FL	-	*- FL
16	1		*FENDER PANEL REAR LH	Repair	1,933.20 FL	-	*- FL
17	1		*WHEELARCH REAR LH	Serviceable	275.40 FL	-	*- FL
18	1		*BUMPER COVER REAR	Buckled / Cracked	561.70 FL	-	*561.70 FL
19	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	-	*- FL
20	1		*TYRE	Serviceable	300.00 FS	-	*- FS
21	1		*RIM	Serviceable	350.00 FS	-	*- FS
22	1		*DOOR FINISHER CLIP KIT FRT RH	Not Necessary	90.00 FS	-	*- FS
23	1		*DOOR MOULDING CLIP L70Y	Not Necessary	80.00 FS	-	*- FS
24	1		*DOOR MOULDING SCREW L70Y	Not Necessary	65.00 FS	-	*- FS
25	1		*DOOR CASING CLIP	Not Necessary	85.00 FS	-	*- FS
26	1		*DOOR STICKER TRANSCAB	Necessary	100.00 FS	-	*60.00 FS
27	1		*DOOR STICKER CLASSIC	Necessary	100.00 FS	-	*15.00 FS
28	1		*DOOR STICKER 6555-3333	Necessary	100.00 FS	-	*60.00 FS
29	1		*BOOT STICKER TRANSCAB	Not Necessary	100.00 FS	-	*- FS
30	1		*BOOT STICKER 65553333	Not Necessary	100.00 FS	-	*- FS
31	2		*WINDSCREEN SEALANT	Not Necessary	150.00 FS	-	*- FS
32	1		*WINDSCREEN MOULDING	Not Necessary	200.00 FS	-	*- FS
33	1		*WINDSCREEN INNER SPONGE SEAL	Not Necessary	130.00 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,227.21	3,541.36
- List Item Discount on L Items 10.00/10.00% (\$)	1,527.72	340.64
Total Parts (\$)	15,699.49	3,200.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	300.00	60.00
2	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
3	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMINGS, GARNISH, FITTINGS AND OTHERS, TO ENABLE REPAIR	New	380.00	0.00
4	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	New	1,400.00	500.00
5	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	240.00	30.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	880.00
7	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			4,280.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >