



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 14.12.2020
Emailed : 05.01.2021, 6.20pm
Date Survey : 15.12.2020

VEHICLE NO : SLF 145 S
MODEL : MIT ASX 2.0
WIP : 60755

Material	:	\$	<u>5,092.01</u>
Labour	:	\$	<u>3,560.00</u>
Sub-Total	:	\$	<u>8,652.01</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>8,652.01</u>
GST 7%	:	\$	<u>605.64</u>
Grand Total	:	\$	<u>9,257.65</u>
Finalise By/Date	:		<u>LOI / 05/01/2021</u>

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

TP claim _____

Claim GIA / LTA fee _____

Claim Loss of Use / Rental

Claim Medical Fee / Others _____

Third Party Report - _____



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 15/12/2020	Cust No/Name	KCV05686/Ko Tuck Chong Willy
	Reg No/Reg Date	SLF145S*DCS3G/ 11/08/2016
	Date In/Mileage	15/12/2020/ 41642
	Chassis/Package	JMFXTGA2WFZC19242 /#
	Engine No	4B11RS3216
	Make/Model	MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim	A03 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	04/01/2021/ 16:51	BLK	260 / AiTing	60755				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E	PNT88000	REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER, RH FRONT FENDER, RH FRONT DOOR, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME							✓ 1350.00
E	PNT98000	RESPRAY ON FRONT BUMPER, RH FRONT FENDER, RH FRONT DOOR, AND ALL OTHER AFFECTED AREAS TO THE SAME							✓ 1050.00
E	PNT88000	TRANSFER RH FRONT DOOR ATTACHMENTS TO NEW PANEL							✓ 120.00
A	WHEELALIGNMENTBP	CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT							✓ 120.00
A	549000099	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							✓ 30.00
A	10028901	CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE							✓ 120.00
M	SUNDRY	APPLY ZERTONA COATING ON AFFECTED AREAS							✓ 240.00
M	SUNDRY	SUNDRIES							✓ 20.00
S	SPECIALISTJOB	TRANSFER RH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING							✓ 30.00
S	TYRESALES2	SUPPLY RH FRONT TIRE							✓ 480.00
X	FACE,FR BUMPER				1.00	✓ 1036.00	23.00	797.72	
X	REINFORCEMENT,FR BUMPER				1.00	✓ 53.00	23.00	40.81	
X	FENDER,FR RH				1.00	✓ 510.00	23.00	392.70	
X	SHIELD,FR WHEELHOUSE,RH				1.00	✓ 146.00	23.00	112.42	
X	PANEL ASSY,FR DOOR,RH				1.00	✓ 882.00	23.00	679.14	
X	MLDG,F/DR WDO BELT LINE,RH				1.00	✓ 130.00	23.00	100.10	
X	GLASS,FR DOOR WINDOW,RH				1.00	✓ 189.00	23.00	145.53	
X	TAPE,FR DOOR SASH				1.00	✓ 36.00	23.00	27.72	
X	GARNISH,FR FENDER,RH				1.00	✓ 89.00	23.00	68.53	

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 15/12/2020	Cust No/Name	KCV05686/Ko Tuck Chong Willy
	Reg No/Reg Date	SLF145S*DCS3G/ 11/08/2016
	Date In/Mileage	15/12/2020/ 41642
	Chassis/Package	JMFXTGA2WFZC19242 /#
	Engine No	4B11RS3216
	Make/Model	MIT/ASX 2.0 CVT 2WD (N04)
	Colour/Trim	A03 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	04/01/2021/ 16:51	BLK	260 / AiTing	60755

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X MIRROR ASSY, DOOR, RH	1.00	✓ 472.00	23.00	363.44
X COVER, DOOR MIRROR, OTR RH	1.00	✓ 138.00	23.00	106.26
X MOULDING, FR WHEEL ARCH, RH	1.00	✓ 132.00	23.00	101.64
X WHEEL, SPARE TIRE DISC	1.00	✓ 1102.00	23.00	848.54
X HEADLAMP ASSY, RH	1.00	824.00	23.00	634.48
X HEADLAMP ASSY, LH	1.00	824.00	23.00	634.48
X CLIP, ENG ROOM COVER	10.00	2.00	23.00	15.40
X CLIP, RR BUMPER	10.00	3.00	23.00	23.10

Z TEXT

AIG OD CLAIM.

DOA : 14.12.20

SURVEYOR STEVE LKK

15.12.20

POLICY NO: 2100477891-03

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,092.01		Nett	8,652.01
Labour	2,790.00	7% GST on	8652.01	605.64
Standard Menu	0.00			
Specialist Job	510.00		Total Payable	9,257.65
Diagnostics Job	0.00			
Sundry/Others	260.00			
Total (w/o GST)	8,652.01			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SLF 145 S

<u>Materials</u>		<u>Cost (\$)</u>
1	Headlamp assy, RH	824.00 ✓ BR
2	Headlamp assy, LH	824.00 ✓ BR
3	Clips (x10)	20.00 ✓ nec
4	Clips (x10)	30.00 ✓ nec
Total		1,698.00
Less 23% discount		390.54
Total after discount		1,307.46
7% GST		91.52
Grand total		<u>\$ 1,398.98</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

Work Order: R001285
 License: SLF 145 S
 Technician: 106 WENG SOON
 Mileage: 41642
 Date: 22.12.20 17:52

Mitsubishi : ASX/RVR : Front Wheel Drive : 2010-

Front : Left

Actual	Before	Specified Range
0°03'	0°03'	-0°15' 0°45'
1°54**	1°54**	2°10' 3°10'
0°03'	0°03'	-0°02' 0°08'
14°41**	14°40**	11°30' 14°30'
14°44'	14°44'	11°15' 15°15'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°06'	-0°06'	-0°15' 0°45'
3°07'	3°07'	2°10' 3°10'
0°03'	0°01'	-0°02' 0°08'
14°32**	14°32**	11°30' 14°30'
14°26'	14°26'	11°15' 15°15'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
0°09'	0°09'	-0°30' 0°30'
-1°13**	-1°13**	-0°30' 0°30'
0°08'	0°09'	
0°06'	0°04'	-0°04' 0°16'
		-2°00' 2°00'

Rear : Left

Actual	Before	Specified Range
-0°51'	-0°49'	-0°55' 0°05'
0°07'	0°11'	0°01' 0°16'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°12**	-1°13**	-0°55' 0°05'
0°09'	0°09'	0°01' 0°16'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
0°21'	0°24'	-0°30' 0°30'
0°17'	0°21'	0°01' 0°31'
-0°01'	0°01'	

All DTCs

Item	Setting	Information
M.U.T.-3 Version		SEW20091-00
V.C.I. Version		B 178
Vehicle Information		GA2W 2015MY

31F1458

Get your parts for me with to Roger all the good

Bob

2020.12.22

All DTCS

2020.12.22

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCS	
AT/CVT/A-MTTC-SST	CVT_14080300		No DTCS	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCS	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCS	
SRS-AIR BAG	ORC_81040000		No DTCS	
Air Conditioner	AC_80080006		No DTCS	
ETACS (Can't see P/N on ECU body)	ETACS_83040900		No DTCS	
Meter	MTR_84084000		No DTCS	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
LIN (Can't see P/N on ECU body)	ETACS_83040900		Non-target System	
KOS/IMMO/keyless/TPMS (IMMOBI & KOS)	KOS_WCM_8A880001_08MY		No DTCS	
OSS	OSS_95040000		No DTCS	

All DTCS

2020.12.22

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
AFS/ACL/Leveling	AFS_90080000		Non-equipped System or Communication Error	
CORNER SENSOR/BACK SENSOR	CornerSens_96000000		Non-equipped System or Communication Error	