



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV05686/Ko Tuck Chong Willy Reg No/Reg Date SLF1455*DCS3G/ 11/08/201 Date In/Mileage 15/12/2020/ 0 Chassis No JMFXTGA2WFZC19242 Engine No 4B11RS3216 Make/Model MIT/ASX 2.0 CVT 2WD (N04) Colour/Trim A03 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	15/12/2020/ 14:14	QUK	282 / Kevin Leong	60755

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, FRT RH FENDER, FRT RH DOOR & AFFECTED AREA	450			1350 1800.00
E PNT98000 PAINT WORK ON FRT BUMPER, FRT RH FENDER & FRT RH DOOR	750			1050.00
E PNT88000 TO TRANSFER FRT RH DOOR ATTACHMENTS TO NEW PANEL				40.00
M SUNDRY PERFORM RUST PREVENTION				450.00
A 33900099 REPLACE FRONT UNDERCARRIAGE				120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				30.00
M SUNDRY TO TRANSFER FRT RH RIM INCLUDING BALANCING				480.00
M SUNDRY TO SUPPLY FRT RH TYRE				30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				240.00
M SUNDRY TO APPLY ZERTONA COATING ON AFFECTED AREA				50.00
M SUNDRY SUNDRIES	1.00	1036.00	23.00	797.72
M FACE,FR BUMPER	1.00	53.00	23.00	40.81
M REINFORCEMENT,FR BUMPER	1.00	135.00	23.00	103.95
M COVER,HEADLAMP SUPT PANEL	1.00	66.00	23.00	50.82
M COVER,FR BUMPER	1.00	510.00	23.00	392.70
M FENDER,FR RH	1.00	146.00	23.00	112.42
M SHIELD,FR WHEELHOUSE,RH	1.00	882.00	23.00	679.14
M PANEL ASSY,FR DOOR,RH	1.00	47.00	23.00	36.19
M W/STRIP,F/DR OPENG,LWR LH				

Estimate

Provide Sales Agent

Confirm & accepted by

 Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV05686/Ko Tuck Chong Willy Reg No/Reg Date SLF1455*DCS3G/ 11/08/201 Date In/Mileage 15/12/2020/ 0 Chassis No JMFXTGA2WF ZC19242 Engine No 4B11R53216 Make/Model MIT/ASX 2.0 CVT 2WD (N04) Colour/Trim A03 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	15/12/2020/ 14:14	QUK	282 / Kevin Leong	60755

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M RUNCHANNEL, F/DR WDO GLA, RH X NM	1.00	143.00	23.00	110.11
M W/STRIP, FR DR OPNG, OTR RH X NM	1.00	168.00	23.00	129.36
M MLDG, F/DR WDO BELT LINE, RH	1.00	130.00	23.00	100.10
M GLASS, FR DOOR WINDOW, RH	1.00	189.00	23.00	145.53
M TAPE, FR DOOR SASH	1.00	36.00	23.00	27.72
M AIR DAM, SIDE, RH X NM	1.00	541.00	23.00	416.57
M GARNISH, FR FENDER, RH	1.00	89.00	23.00	68.53
M MIRROR ASSY, DOOR, RH	1.00	472.00	23.00	363.44
M COVER, DOOR MIRROR, OTR RH	1.00	138.00	23.00	106.26
M MOULDING, FR WHEEL ARCH, RH	1.00	132.00	23.00	101.64
M WHEEL, SPARE TIRE DISC	1.00	1102.00	23.00	848.54
M STRUT, FR SUSP, RH	1.00	484.00	23.00	372.68
M LINK, FR SUSP STABILIZER	1.00	137.00	23.00	105.49
M PAD, FR SUSP SPRING, LWR	1.00	15.00	23.00	11.55
M BEARING, FR SUSP STRUT	1.00	27.00	23.00	20.79
M DAMPER, FR SUSP STRUT	1.00	39.00	23.00	30.03
M GEAR & LINK ASSY, STEERING	1.00	1211.00	23.00	932.47

Steve CLKK) OD- NM AL
 15/12/20 Excess - ?
 3.00pm P/P
 Ry Bel Sny
 7 dys

Estimate

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To replace damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

	Nett	10,634.56
7% GST on	10634.56	744.42
Total Payable		11,378.98

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.