

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

15-Dec-20

ESTIMATE REPAIR BILL FOR TOYOTA ALTIS REGN NO: SLV 7163 J

2 pcs	n/s & o/s Tail lamp @\$389.50	\$	779.00	14-? R4X
2 pcs	n/s & o/s reflector @\$307.32	\$	614.64	X
1 pc	Bootlid	\$	845.30	R4
1 pc	Bootlid lock	\$	63.50	X
1 pc	Bootlid lock catch	\$	40.00	X
1 pc	Bootlid emblem "Toyota Corolla"	\$	68.00	new
1 pc	Bootlid emblem "Corolla"	\$	30.00	new
1 pc	Bootlid emblem "Toyota logo"	\$	30.00	new
1 pc	Bootlid emblem "Altis"	\$	48.00	new
1 pc	Bootlid chrome moulding	\$	76.00	X
2 pcs	Bootlid hinges @\$60.00	\$	120.00	X
1 pc	Rear bootlid weatherstrip	\$	63.10	new
1 pc	Rear bumper	\$	487.00	new
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00	\$	58.00	new
1 pc	Rear bumper reinforcement	\$	395.00	new
1 pc	End panel	\$	650.00	? photo
1 pc	End panel top garnish	\$	88.90	new - photo
		\$	4,456.44	
Less 25%		\$	1,114.11	
		\$	3,342.33	

S/NETT

1 set	Rear bumper clips	\$	35.00	30 new
1 set	Reverse sensor	\$	280.00	200 new

15-Dec-20

ESTIMATE REPAIR BILL FOR TOYOTA ALTIS REGN NO: SLV 7163 J

Sundry	\$	50.00	20
To dismantle and replace new reverse sensor and reset to the same	\$	80.00	30
To dismantle / refit the inner garnish, inner lining, inner trim, cushion seat, etc to facilitate repair	\$	200.00	60
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the end panel. Including knock-out, straighten, repair, reshape and adjust of the rear n/s & o/s fender	\$	1,000.00	600.
To putty and spray painting on the bootlid, rear bumper, end panel, rear o/s & n/s fender	\$	1,250.00	600
To apply rustproofing on the repaired and replaced panels.	\$	200.00	30
	\$	<u>6,437.33</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanfuhi 9749 5749
- WP 15/12/20 1430.
~~Lump sum~~
Plp 4 Resurvey before paint.
05 days.
Tanfuhi C Khamto. 10/12/20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: