

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 17 Dec 2020

Preliminary Advice

Insured Vehicle No : GZ5548J
TP Vehicle No : GBK982J
Make : HONDA ACCORD
Date of Inspection : 16/12/2020
Inspection At : YEW TEE AUTOMOBILE TECH PTE LTD (KAKI BUKIT)
BLK 25 KAKI BUKIT ROAD 4, #01-61 SYNERGY @ KAKI BUKIT
SINGAPORE 417800

Accident Date : 04/12/2020
Assignment Date : 15/12/2020
Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,515.70
Revised Amount	:S\$	2,892.59
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,892.59

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : survey on wp