

ASS. REC. BY:

REF:

AG / 200138731K7

C

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

176 05

King's

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

1-B1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Ah Hway

Veh No:

SMU 8473B Yr Regn: 08, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mazda 2

c.c

1496

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

4909

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM60J2HA01300492

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

11/12/20

D.O.I.

16/12/202

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/1 03753.40 Confirmed Cred: 1487.40, 28%

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Liao weiliang

King's Auto Spray Paint Pte Ltd  
Blk 160 Sin Ming Drive #05-10  
sin ming Auto City Singapore 575722

Not Authorized  
Resurvey B4 painting

15-12-20 5day

Re: Estimate cost for SMU 8473B MAZDA 83753.40

SUPPLY OF PARTS:

|                                             |     |       |            |      |
|---------------------------------------------|-----|-------|------------|------|
| 1pc front bonnet                            | 738 | Bu    | \$ 738     | ✓    |
| 1pc front bonnet outer rubber               |     | In    | 60         | +    |
| 1pc front bonnet inner rubber               |     | In    | 36         | +    |
| 18pc front bonnet rubber clips outer @ 5.00 |     | In    | 90         | —    |
| 2pc front bonnet rubber clips inner @ 5.00  |     | In    | 10         | —    |
| 1pc front bonnet lock                       |     | R     | 179        | X    |
| 1pc front bumper                            | 874 | Bu    | 874        | —    |
| 10pc front bumper top clips @ 5.00          |     | In    | 50         | ✓    |
| 2pc front bumper side retainer @ 18.00      |     | disin | 36         | +    |
| 2pc front bumper side cover @ 45.00         |     | In    | 90         | X    |
| 1pc front bumper lower grille               |     | CM    | 93         | ✓    |
| 1pc front bumper beam                       |     | R     | 526        | X    |
| 2pc front bumper brackets @ 25.00           |     | R     | 50         | X    |
| 1pc front bumper sponge inner               |     | CM    | 128        | ✓    |
| 5pc front bumper clips @ 5.00               |     | In    | 25         | —    |
| 1pc front grille                            |     | In    | 91         | —    |
| 1pc front grille logo                       |     | In    | 34         | —    |
| 5pc front grille rivet @ 10.00              |     | In    | 50         | —    |
| 2pc front grille side mldg @ 167.00         |     | disin | 334        | +    |
| 2pc front Head lamp @ 581.00                |     | disin | 1162       | +    |
| 2pc front Head lamp garnish @ 35.00         |     | CM    | 70         | X    |
|                                             |     | In    | \$         |      |
|                                             |     |       | \$4726.00  |      |
|                                             |     |       | 945.20     |      |
|                                             |     |       | 3780.80    |      |
|                                             |     | Scr   | 30.00      | 25in |
|                                             |     |       | 30.00      | 20   |
|                                             |     |       | \$ 700.00  | 500  |
|                                             |     |       | \$ 7.00.00 | 550  |
|                                             |     |       | 5240.80    |      |

Less 20%

LABOUR:

1pc front number plates  
check wiring

To renew the above mentioned Parts  
Knocking, cutting, welding (straighten front  
damaged parts

spray paintings

LKK Auto Consultants hence notify  
the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary item(s) must be resurveyed and  
submitted for approval from Insurance Company

Signature:  
Date:

King's Auto Spray Paint Pte Ltd  
Blk 160 Sin Ming Drive #05-10  
Sin Ming Autocity Singapore 575722

Liao Weiliang

17-12-20

Re: Supplementary Est for SMU8473B  
SUPPLY OF PARTS

ipc front support panel

~~RM~~ \$ 374.00 ✓

Less 20%

74.80

---

\$ 299.20