

ASS. REC. BY:

REF:

CS/CT/12003881/Atd3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: GBF 99R

Policy No. DMCVSN WD 00089842001

Claims No. SNM20D 204867/102

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 6BC7174X Yr Regn: 2013 / Augnt

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna c.c. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 376299 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFAT35Y10K202479

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15C BS

R: 155 R12C Fullcer

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____ D.O.I. 04/01/21

Survey held at SME

Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP China</u>
	<u>Confirm lump sum \$9300. 4 days</u>
	<u>(Red: 7622.25 : 45%)</u>
	<u>MV : 32K</u>
	<u>PV : 17.3K</u>
	<u>Nett: 14.7K</u>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.H (\$ 9300)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ \$ + RS. ____ SI

Photos

Others

TOTAL



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	14/12/2020 17:37 (SGT)
Date of Accident	12/12/2020 17:50 (SGT)
Exact Location of Accident	CTE, Singapore
Additional Location Information	CTE TOWARDS SLE BEFORE EXIT JALAN BAHAGIA.
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC7174X
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BENGAWAN SOLO PTE LTD
Company Reg No	1XXXXX507H
Email Address	chuang.he@bengawansolo.com.sg
Mobile Phone No	(Phone) +65-97638927
Alternative Phone No	(Office) +65-67569098

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company	Axa
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	P0351841
Cover Note Number	-

DRIVER

Name of Driver	MARAN A/L L ELANCHERAN
Passport No/FIN	GXXXX269N
Date Of Birth	15/03/1994
Occupation	Outdoor



Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBG3544S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	507H
Vehicle Details	
Vehicle No.:	GBC7174X
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Jan 2021
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	1KD2316535
Chassis No.:	JTFAT35Y10K202479
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	30 Aug 2013
First Registration Date:	30 Aug 2013
Transfer Count:	0
Actual ARF Paid:	\$1,249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$65,036.00
COE Rebate Amount:	\$17,238.00
Total Rebate Amount:	\$17,238.00

The information contained herein is correct as at 04 Jan 2021

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)





Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

 Post an Ad |
  Advertiser Login |
  Ways of Selling

2015 Volkswagen Golf 1.2A TSI At \$46800.



Well Kept Interior, Wear And Tear Parts Changed. Low Depreciation As Well.
Hamilton Autohub StarAd



PRIME MOTOR & LEASING

(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Browse by Category  [Save Search](#) [Print](#) [Sort by Date Posted](#)  20 results/page 

3 vehicles **Search** [Advanced Search](#) [Search](#) [View All](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Dyna		Any	Any	2013	Any	Any	Any	Available
	☐ Toyota Dyna 150 3.0M		\$28,000	\$12,420 /yr	08-Apr-2013	2,982 cc	-	Truck	Available
Fuel Type: Diesel Great For Preserving Food.									
 Posted: 19-Dec-2020 Tags: 2013 Toyota Dyna, Toyota Dyna, Toyota, Dyna									
	☐ Toyota Dyna 150 3.0M		\$28,800	\$12,710 /yr	12-Apr-2013	2,982 cc	-	Truck	Available
Fuel Type: Diesel Rare Toyota Dyna 150 10 Feet Truck With Mitsubishi TD22D Freezer. Can Reach -12 Degree In Less Than 1hr Time. Very Well Maintained And Regular Service Just Done. Call Now.									
 Posted: 22-Dec-2020 Tags: 2013 Toyota Dyna, Toyota Dyna, Toyota, Dyna									
	☐ Toyota Dyna 150 3.0M		\$27,800	\$12,230 /yr	15-Apr-2013	2,982 cc	-	Truck	Available
Fuel Type: Diesel All Time Favorite Toyota Dyna 10ft Lorry. Well Known For Its Reliability & Durability With Low Maintenance Costs. High Body Trade In Value Once COE Finish. Call For Appointment Before Coming.									
 Posted: 21-Dec-2020 Tags: 2013 Toyota Dyna, Toyota Dyna, Toyota, Dyna									

Save this search criteria, to get email alerts whenever a match is found. [Save Search](#)

Make  Model  Price  Depreciation  Reg Date  Eng Cap  Mileage  Veh Type  Status 

For old advertisements, view [Expired ads](#) 20  results/page

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 63896111 FAX: 62247478

ATTN: Motor Claim Department

Your Ref No : 20/CN/TP-155(12)

Claim Type : Third Party

Accident Date : 12/12/2020

TP Veh Reg No : GBF998R

Claim No :

No : EST20121401

Date : 14/12/2020

Policy No : GA0351841

Veh Reg No : GBC7174X

Make / Model : TOYOTA DYNA

Chasis No : 0

Engine No :

Reg. No :

ESTIMATE FOR VEHICLE NO: GBC7174X

Discription	Quantity	Unit Price	Amount
LIST PRICE			S\$ S\$
1 FRT PANEL <i>Dented</i>	1 PC		✓ \$1,300.00
2 FRT GRILLE <i>Cracked</i>	1 PC		✓ \$650.00
3 GRILLE LOGO <i>new</i>	1 PC		✓ \$80.00
4 GRILLE SEAL <i>new</i>	1 PC		X? \$55.00
5 GRILLE CLIPS <i>new</i>	6 PCS	\$5.00	✓ \$30.00
6 FRT PANEL "DYNA" PLATE <i>new</i>	1 PC		✓ \$85.00
7 HEADLAMP <i>Cracked</i>	2 PC	\$850.00	? \$1,700.00 ✓
8 HEADLAMP LOWER SEAL <i>new</i>	2 PC	\$55.00	X+ \$110.00
9 FRT BUMPER <i>Dislodge</i>	1 PC		✓ \$535.00
10 FRT BUMPER REINFORCEMENT <i>Dented</i>	1 PC		? \$240.00 ✓
11 FRT BUMPER BRACKET <i>new</i>	2 PC	\$105.00	X? \$210.00
12 FRT NOZZLE <i>new</i>	2 PC	\$55.00	X+ \$110.00
13 FRT WIPPER ARM RH <i>new</i>	1 PC		X+ \$115.00
14 FRT WIPPER ARM CAP RH <i>new</i>	1 PC		X+ \$38.00
15 FRT WINDSCREEN RUBBER <i>new</i>	1 PC		X+ \$355.00
16 TAIL LAMP <i>new</i>	2 PC	\$265.00	X+ \$530.00
TOTAL			\$6,143.00
-25.00%			\$1,535.75
			\$4,607.25

SPECIAL NET

1 REAR STAINLESS STEEL DOOR FRAM <i>Dented</i>	1 PC		\$1,650.00 <i>new</i>
2 REAR DOOR PANEL WITH ALL ROUND GASKET <i>Cracked</i>	2 PC	\$950.00	✓ \$1,900.00
3 DOOR GASKET 85MM <i>new</i>	2 PC	\$100.00	✓ \$200.00
4 RIGHT SIDE PANEL REAR <i>Cracked</i>	1 PC		1400 8 \$1,850.00
5 FIBER CORNER GUARD 10FT <i>Not new</i>	1 PC		X+ \$300.00
6 FIBER END CAP <i>new</i>	2 PC	\$30.00	X+ \$60.00
7 REAR DOOR LOCK HANDLE <i>new</i>	2 PC	\$200.00	X+ \$400.00
8 REAR DOOR T HOOK <i>new</i>	2 PC	\$10.00	X+ \$20.00
9 REAR FIBRE DOOR FRAME <i>new</i>	2 PC	\$480.00	X+ \$960.00
10 STAINLESS STEEL RAIN COVER <i>Not new</i>	1 PC		X+ \$90.00
11 FRT DOOR COMPANY STICKER <i>new</i>	1 PC		5225 \$25.00
12 REAR REINFORCEMENT BAR <i>Best</i>	1 PC		500 \$750.00
13 REAR RUBBER BUSH STOPPER <i>lit</i>	2 PCS	\$150.00	✓ \$300.00
TOTAL			\$8,505.00

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 63896111 FAX: 62247478

ATTN: Motor Claim Department

Your Ref No : 20/CN/TP-155(12)

Claim Type : Third Party

Accident Date : 12/12/2020

TP Veh Reg No : GBF998R

Claim No :

No : EST20121401

Date : 14/12/2020

Policy No : GA0351841

Veh Reg No : GBC7174X

Make / Model : TOYOTA DYNA

Chasis No : 0

Engine No:

Reg. No :

ESTIMATE FOR VEHICLE NO: GBC7174X

Discription	Quantity	Unit Price	Amount
Labour			
1 WIRE CHECKING			\$40.00 30
2 REMOVE & REFIX FRT WINDSCREEN			\$120.00 ✓
3 REMOVE & REFIX DASHBOARD			\$250.00 +200
4 REMOVE & REFIX AIRCON BLOWER & GAS			X\$150.00 5
5 LABOUR CHARGE FRONT			\$800.00 700
6 PAINTING			\$850.00 600
7 LABOUR CHARGE REAR:			\$1,600.00 1000
- TO CARRY OUT BOX ACCIDENT REPAIR			
- TO SUPPLY LABOUR, MATERIAL AND EQUIPMENT			
- TO DISMANTLE AND REPLACE THE ABOVE PARTS			
- TO REPLACE CONCEAL INTERIOR AND EXTERIOR OF BOX			
- TO ASSEMBLE DOOR PANEL & REALIGNMENT			
- TO FINAL TOUCH UP AND CLEANING			
TOTAL			\$3,810.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Amount Before Excess \$16,922.25
Add GST @7% \$1,184.56
Total Amount Payable \$18,106.81

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE

total: 11606.25
L/S: 9.31k

Adrian Lj
L/S 04/01/21
14 Days

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 FAX: 62247478
ATTN: Motor Claim Department
Your Ref No : 20/CN/TP-155(12)
Claim Type : Third Party
Accident Date : 12/12/2020
TP Veh Reg No : GBF998R

Claim No :
No : EST20121401
Date : 14/12/2020
Policy No : GA0351841
Veh Reg No : GBC7174X
Make / Model : TOYOTA DYNA
Chasis No : 0
Engine No :
Reg. No :

ESTIMATE FOR VEHICLE NO: GBC7174X

Discription	Quantity	Unit Price	Amount
LIST PRICE			S\$ S\$
1 FRT PANEL <i>Dented</i>	1 PC		✓ \$1,300.00
2 FRT GRILLE <i>Cracked</i>	1 PC		✓ \$650.00
3 GRILLE LOGO <i>New</i>	1 PC		✓ \$80.00
4 GRILLE SEAL <i>?</i>	1 PC		✓ \$55.00
5 GRILLE CLIPS <i>New</i>	6 PCS	\$5.00	✓ \$30.00
6 FRT PANEL "DYNA" PLATE <i>New</i>	1 PC		✓ \$85.00
7 HEADLAMP <i>Cracked</i>	2 PC	\$850.00	✓ \$1,700.00
8 HEADLAMP LOWER SEAL <i>New</i>	2 PC	\$55.00	✓ \$110.00
9 FRT BUMPER <i>Dented</i>	1 PC		✓ \$535.00
10 FRT BUMPER REINFORCEMENT <i>?</i>	1 PC		✓ \$240.00
11 FRT BUMPER BRACKET <i>?</i>	2 PC	\$105.00	✓ \$210.00
12 FRT NOZZLE <i>New</i>	2 PC	\$55.00	✓ \$110.00
13 FRT WIPPER ARM RH <i>?</i>	1 PC		✓ \$115.00
14 FRT WIPPER ARM CAP RH <i>?</i>	1 PC		✓ \$38.00
15 FRT WINDSCREEN RUBBER <i>New</i>	1 PC		✓ \$355.00
16 TAIL LAMP <i>New</i>	2 PC	\$265.00	✓ \$530.00
TOTAL			\$6,143.00
-25.00%			\$1,535.75
			\$4,607.25

5225
20/12/25

SPECIAL NET			
1 REAR STAINLESS STEEL DOOR FRAM <i>Dented</i>	1 PC		\$1,650.00 <i>New</i>
2 REAR DOOR PANEL WITH ALL ROUND GASKET <i>Cracked</i>	2 PC	\$950.00	✓ \$1,900.00
3 DOOR GASKET 85MM <i>New</i>	2 PC	\$100.00	✓ \$200.00
4 RIGHT SIDE PANEL REAR <i>Cracked</i>	1 PC	1400.00	✓ \$1,850.00
5 FIBER CORNER GUARD 10FT <i>?</i>	1 PC		✓ \$300.00
6 FIBER END CAP <i>?</i>	2 PC	\$30.00	✓ \$60.00
7 REAR DOOR LOCK HANDLE <i>New</i>	2 PC	\$200.00	✓ \$400.00
8 REAR DOOR T HOOK <i>New</i>	2 PC	\$10.00	✓ \$20.00
9 REAR FIBRE DOOR FRAME <i>New</i>	2 PC	\$480.00	✓ \$960.00
10 STAINLESS STEEL RAIN COVER <i>?</i>	1 PC		✓ \$90.00
11 FRT DOOR COMPANY STICKER <i>New</i>	1 PC		✓ \$25.00
12 REAR REINFORCEMENT BAR <i>Best</i>	1 PC		✓ \$750.00
13 REAR RUBBER BUSH STOPPER <i>ut</i>	2 PCS	\$150.00	✓ \$300.00
TOTAL			\$8,505.00

5225

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 63896111 FAX: 62247478

ATTN: Motor Claim Department

Your Ref No : 20/CN/TP-155(12)

Claim Type : Third Party

Accident Date : 12/12/2020

TP Veh Reg No : GBF998R

Claim No :

No : EST20121401

Date : 14/12/2020

Policy No : GA0351841

Veh Reg No : GBC7174X

Make / Model : TOYOTA DYNA

Chasis No : 0

Engine No:

Reg. No :

ESTIMATE FOR VEHICLE NO: GBC7174X

	Discription	Quantity	Unit Price	Amount
	<u>Labour</u>			
1	WIRE CHECKING			\$40.00 30
2	REMOVE & REFIX FRT WINDSCREEN			\$120.00 ✓
3	REMOVE & REFIX DASHBOARD			\$250.00 1.200
4	REMOVE & REFIX AIRCON BLOWER & GAS			\$150.00 5
5	LABOUR CHARGE FRONT			\$800.00 700
6	PAINTING			\$850.00 600
7	LABOUR CHARGE REAR:			\$1,600.00
	- TO CARRY OUT BOX ACCIDENT REPAIR			1000
	- TO SUPPLY LABOUR, MATERIAL AND EQUIPMENT			
	- TO DISMANTLE AND REPLACE THE ABOVE PARTS			
	- TO REPLACE CONCEAL INTERIOR AND EXTERIOR OF BOX			
	TO ASSEMBLE DOOR PANEL & REALIGNMENT			
	- TO FINAL TOUCH UP AND CLEANING			2650
TOTAL				\$3,810.00

L- 3731.25
SN 5225
LC 2650
11,606.25

48 9300
=

Amount Before Excess \$16,922.25
Add GST @7% \$1,184.56
Total Amount Payable \$18,106.81

For SME MOTOR PTE LTD

AUTHORISED SIGNATURE

14 days

13/01/2021

Adrian Lj
L/s 04/01/2021

14 Days