

ASS. REC. BY:

REF: PCZ / 200138841ke

C

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / PWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 839K

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT
Winnie

Date / Time

Action / Instruction

/ Est not ready11/3 11 Pm 83300L CordunVeh No: GBE 6606MYr Regn: 02, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: NIS NV350c.c. 2488Colour: Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 68/209

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JNIMC 2 E 26 E 000 6062Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NIL / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 9 mmR/Bal. 7 mmL/Bal. 9 mmL/Bal. 7 mmD.O.A. 1 / 12 / 20D.O.I. 6 / 1 / 2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopteltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 01/12/2020
TP Veh Reg No: SHB3112K

Estimate No: ES2100001

Date: 06 Jan 2021

Policy No:

Veh Reg No: GBE6606M

Make/Model: NISSAN NV350 PANEL
VAN 2.5 5AT 5DR EURO
V

Chassis No: JN1MC2E26Z0006062

Engine No: YD25389903A

Reg. Date: 22/02/2016

*Not Withheld
11 Day @ 3300/hr
Prummy After Paint*

5 days

Estimate Repair Cost to Vehicle No :GBE6606M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR TYRE - LH 195R15C8PB	300.00	1 PC	<i>2</i> 300.00 <i>X</i>	
2 REAR WHEEL RIM - LH	260.00	1 PC	<i>2</i> 260.00 <i>X</i>	
3 REAR WHEEL RIM CAP - LH	185.00	1 PC	<i>0d/cn</i> 185.00 <i>✓</i>	
			745.00	745.00
Spare Parts				
4 AXLE OIL	40.00	1 LIT	<i>12</i> 40.00 <i>fix X</i>	
5 REAR AXLE - LH	1,680.00	1 PC	<i>5m</i> 1,680.00 <i>X</i>	
6 REAR AXLE BEARING - LH	220.85	1 PC	<i>2</i> 220.85 <i>2</i>	
7 REAR AXLE SHAFT - LH	930.25	1 PC	<i>Ry</i> 930.25 <i>2</i>	
8 REAR BUMPER	683.60	1 PC	<i>2</i> 683.60 <i>X</i>	
9 REAR BUMPER BRACKET - LH	48.00	1 PC	<i>5m</i> 48.00 <i>X</i>	
10 REAR FENDER - LH <i>2006.90</i>	2,680.00	1 PC	<i>Ry</i> 2,680.00 <i>✓</i>	
11 REAR FENDER INNER PANEL - LH	685.15	1 PC	<i>2</i> 685.15 <i>X</i>	
12 REAR FENDER MUD FLAP - LH	185.00	1 PC	<i>5m</i> 185.00 <i>X</i>	
13 REAR SHOCK ABSORBER - LH	425.10	1 PC	<i>2</i> 425.10 <i>X</i>	
14 TAIL LAMP LH <i>10%</i>	331.40	1 PC	<i>2</i> 331.40 <i>X</i>	
			7,909.35	7,909.35
Labour				
15 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,200.00	1 JOB	2,200.00 <i>600</i>	
16 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00 <i>500</i>	
17 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00 <i>300</i>	
			4,200.00	4,200.00


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722

Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031

Email: yeeautopte ltd@gmail.com

Registration No.: 201719251W GST No: 201719251W

M/S : First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 01/12/2020
TP Veh Reg No: SHB3112K

Estimate No: **ES2100001**
Date: 06 Jan 2021
Policy No:
Veh Reg No: **GBE6606M**
Make/Model: NISSAN NV350 PANEL
VAN 2.5 5AT 5DR EURO
V
Chassis No: JN1MC2E26Z0006062
Engine No: YD25389903A
Reg. Date: 22/02/2016

Estimate Repair Cost to Vehicle No :GBE6606M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 12,854.35
			Add GST @ 7%	899.80
			Total Amount Payable	S\$ 13,754.15

TOTAL: SINGAPORE DOLLAR THIRTEEN THOUSAND SEVEN HUNDRED FIFTY FOUR AND CENTS FIFTEEN ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE