

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road,#17-00 Tower Block  
MND Complex  
Singapore 069110

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jaime Tay

Date: 25 Feb 2021

## **Preliminary Advice**

Insured Vehicle No : GBD4590S  
TP Vehicle No : SLF1974J  
Make : MAZDA 3  
Date of Inspection : 05/01/2021  
Inspection At : PROGRESSIVE CAR CARE PTE LTD (HQ)  
BLK 3022A UBI ROAD 1, #01-45/46  
SINGAPORE 408716

Accident Date : 11/12/2020  
Assignment Date : 16/12/2020  
Est. Duration of Repair : 3

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,398.10
Revised Amount	:S\$	1,710.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,710.90
Lump Sum Repair	:S\$	1,350.00

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : survey on wp