



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd
(Co. Reg. No. 201006949C)
Blk 3022A Ubi Road 1 #01-45/ 46 S408716
T: +65 6741 5336 | F: +65 6741 7208
E: claims@procarcare.com.sg
W: www.procarcare.com.sg

TP INSURER: EQ Insurance Company Ltd (HQ)
NA

Singapore

PARTICULARS OF CLAIM			
Claim Type:	THIRD PARTY	Ref. No:	TP 1220-6181
Policy No:		Date of Loss:	11/12/2020
Vehicle Reg. No.:	SLF1974J	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	KWA CHU KIT		
Make/Model:	MAZDA 3, 1.4 SEDAN 1.5L SP.6EAT (A)	Vehicle Reg. Date:	17/08/2016
Vehicle Colour:	BLUE	Chassis No:	JM6BM42A8G0344254
Engine No:	P520370580		
Odometer:	63085 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	PROGRESSIVE CAR CARE PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	1,068.10
Miscellaneous Items	0.00
Labour	730.00
Paintwork Labour	600.00
Towing	0.00
Gross Total (S\$)	2,398.10
+ GST 7.00% (S\$)	167.87
Nett Amount (S\$)	2,565.97

This claim is handled by: LILY LIM

*not Authorized
Lily
5/1/21
@ 9-15am
take photo after rep
3 days*

Generated using Merimen e-Claims Internet Estimate and Adjusting System

LKK Auto Consultants is on behalf of the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Dec 2020)
Parts: 143 MAZDA 3 1.4 SEDAN 1.5L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Progressive Car Care Pte Ltd/SLF1974J/14/12/2020 12:47
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BUMPER WITH LOWER GARNISH; BLACK <i>DO/OC</i>	0.00	0.00	*370.00 F ✓
2	1	NA	*REAR BUMPER TOW COVER - LH <i>m.s</i>	0.00	0.00	*29.00 F ✓
3	2	NA	*REAR BUMPER SIDE HOLDER - LH/RH <i>AM</i>	0.00	0.00	*32.00 F X
4	10	NA	*REAR BUMPER CLIPS <i>03.00</i> <i>all</i>	0.00	0.00	*30.00 F ✓
5	1	NA	*REAR BUMPER REINFORCEMENT <i>DO</i>	0.00	0.00	*190.00 F ✓
6	4	NA	*REAR BUMPER SENSOR <i>SHHD</i>	0.00	0.00	*320.00 F ✓
						<i>2005/N</i>
Sub Total (\$\$)						971.00
+ Margin on L,N Items 10.00% (\$\$)						97.10
Total Parts (\$\$)						1,068.10

F=Franchise part.

Progressive Car Care Pte Ltd/SLF1974J/14/12/2020 12:47. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Handwritten calculation:
 7-619
 10%

 680-90
 1710-90
 200

 1368

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	400 600.00
Labour Items			
2	TO KNOCK OUT DENTS ON REAR PANEL; CUT/WELD & REPLACE ACCIDENT PARTS	New	300 500.00
3	TO CHECK WIRING	New	20 20.00
4	TO TRANSFER REAR BUMPER SENSOR	New	50 100.00
5	TO REMOVE; REFIT REAR GARNISH	New	60 80.00
6	TO TUFF-KOTE	New	19x 30.00
Gross Labour Cost (\$\$)			1,330.00

Progressive Car Care Pte Ltd/SLF1974J/14/12/2020 12:47. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

430

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.