



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 04/12/2020

ESTIMATE

NO : QUOT202012-000037(00)

DATE : 09/12/2020

POLICY NO : 999995580

VEH REG NO : GBJ8965L

MAKE/MODEL : VOLKSWAGEN T6 VAN TDI
NWB DSG

CHASSIS NO : WV1ZZZ7HZKH032202

ENGINE NO : CXH179395

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : GBJ8965L

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	Bu 1,180.00	1,180.00 ✓
2 Bonnet hinges - LH/RH	2	95.00	190.00 7X
3 Bonnet lower lock	1	115.00	115.00 7X
4 Support Panel	1	780.00 CM	780.00 ✓
5 Brace panel	1	155.00	155.00 7✓
6 Front grille logo	1	75.00 miy	75.00 ✓
7 Front grille logo plate	1	35.00 miy	35.00 ✓
8 Front grille logo base	1	58.00 CM	58.00 ✓
9 Headlamp assy - LH/RH	2	CM 485.00	970.00 ✓
10 Front bumper	1	880.00 Bu	880.00 ✓
11 Front bumper reinforcement	1	520.00	520.00 7✓
12 Front bumper reinforcement cover	1	198.00	198.00 7X
13 Front bumper brackets - RH / LH	2	45.00	90.00 7
14 Front bumper side retainer - LH/RH	2	28.00 miy	56.00 ✓
15 Front bumper sponge	1	50.00	50.00 7X
16 Front bumper moulding - RH / LH	2	65.00 NIP	130.00 X
17 Air-con condenser	1	850.00	850.00 7✓
18 Radiator assy (inner)	1	385.00	385.00 7✓
19 Radiator assy (outer)	1	580.00	580.00 7✓
20 Inter-cooler assy	1	680.00	680.00 7
			7,977.00
		Add 10%	797.70
			8,774.70
SPECIAL NET			
21 Radiator coolant (tin)	2	60.00 Na	120.00 50SN
22 Front number plate	1	40.00 Na	40.00 ✓
			160.00 (90)
LABOUR			
23 To remove and refix air-con condensor, radiator, inter cooler assy and refill air-con gas.	1	150.00	150.00 100L
24 To panel beat and straighten front chasis frame, front lower cross member, including replacement of parts and align where necessary, to refit and adjust the same.	1	1,000.00	1,000.00 500L
25 To check and rectify wiring system	1	80.00	80.00 20L
26 To putty and spray paint on affected areas.	1	1,000.00	1,000.00 400L

Not Notched
Recovery B4 paint

16/12/2020 [Signature]

\$ 7,939.00
10% 793.90
\$ 8,732.90

puddle - RH \$35/-



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 04/12/2020

ESTIMATE

NO : QUOT202012-000037(00)

DATE : 09/12/2020

POLICY NO : 999995580

VEH REG NO : GBJ8965L

MAKE/MODEL : VOLKSWAGEN T6 VAN TDI
NWB DSG

CHASSIS NO : WV1ZZZ7HZKH032202

ENGINE NO : CXH179395

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : GBJ8965L

Description	Quantity	Unit Price	Amount
		S\$	S\$
27 To supply artwork and paste sticker on bonnet. (Inured ??)	1	220.00	220.00
			2,450.00
		TOTAL	S\$ 11,384.70
		ADD GST @ 7%	796.93
		GRAND TOTAL	S\$ 12,181.63

SINGAPORE DOLLAR TWELVE THOUSAND ONE HUNDRED EIGHTY-ONE AND CENTS SIXTY-THREE ONLY

Parts: \$ 8,732.90
SN 90.00
Labour: 1,170.00
\$ 9,992.90
XS 1,400.00
\$ 8,592.90
7% 601.50
\$ 9,194.40

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

IN : MOTOR CLAIM DEPT

: 6419 3000

FAX : 6415 3723

UR REF NO :

IM TYPE : OWN DAMAGE

CIDENT DATE : 04/12/2020

ESTIMATE

NO : QUOT202012-000037(00)

DATE : 18/12/2020

POLICY NO : 999995580

VEH REG NO : GBJ8965L

MAKE/MODEL : VOLKSWAGEN T6 VAN TDI NWB
DSG

CHASSIS NO : WV1ZZZ7HZKH032202

ENGINE NO : CXH179395

REG. DATE : 2019

Estimate Repair Cost to Vehicle No : GBJ8965L

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Radiator fan motor assy	1 <i>cm</i>	1,380.00	1,380.00 ✓
			1,380.00
		Add 10%	138.00
			1,518.00
		TOTAL	S\$ 1,518.00
		ADD GST @ 7%	106.26
		GRAND TOTAL	S\$ 1,624.26

SINGAPORE DOLLAR ONE THOUSAND SIX HUNDRED TWENTY-FOUR AND CENTS TWENTY-SIX ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE