




STUTTGART AUTO PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



CHINA TAIPING INSURANCE (SINGAPORE)		NAME :	Mr Virupattur Sridharan Sudarsan		WIP :	11793	
3 Anson Road		ADDRESS :	Blk 638 Pasir Ris Drive 1		EXCESS :		
#16-00 Springleaf Tower			#09-554		DATE :	9-Dec-20	
Singapore 079909			Singapore 510638				
ATTN. : MOTOR CLAIMS		TEL :					
FAX :							
VEH NO :	SMA1783H	DATE IN :		CONTACT PERSON :	EVA	63310683	
CHASSIS NO :	WP0ZZZ97ZJL181292	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY		
MODEL :	Panamera 4 Sport Turismo	DATE REG.:	15-Nov-18	POLICY NO. :			

NATURE OF WORKS

S/NO	Parts Description				REVISED	PRICES
	QTY					
1	FRONT BUMPER <i>SCA</i>	1	P971-898-010- -		\$	2,198.80 ✓
2	FRONT BUMPER SPOILER <i>de</i>	1	P971-807-541- -OK1		\$	677.50 ✓
3	FRONT GRILLE <i>SCA</i>	1	P971-807-683-B -OK1		\$	288.70 ✓
4	FRONT GRILLE LH <i>SCA X SMC</i>	1	P971-807-681- -OK1		\$	120.80
5	FRONT GRILLE INSERT TRIM LH ? <i>for</i>	1	P971-807-485- -OK1		\$	97.60
6	FRONT GRILLE SUPPORT DISC ? <i>X SMC</i>	1	P971-807-985- -OK1		\$	92.80
7	DISC BLACK MAT ? <i>SCA</i>	1	P971-807-877- -OK1		\$	125.50 ✓
8	CAMERA HOUSING <i>X SMC</i>	1	P971-807-762- -OK1		\$	42.20
9	BRACKET FOR CAMERA <i>X SMC</i>	1	P971-807-997- -		\$	39.50
10	SENSOR ? <i>X SMC</i>	6	P5Q0-919-275-B -G2X		\$	1,485.00
11	SENSOR GASKET <i>SCA</i>	6	P5Q0-919-133- -9B9		\$	18.60 ✓
12	NUMBER PLATE BRACKET <i>SCA</i>	1	P971-807-999- -OK1		\$	83.50 ✓
13	FOAM PART LH <i>SCA</i>	1	P971-807-251- -		\$	55.50 ✓
14	FOAM PART RH <i>SCA</i>	1	P971-807-252- -		\$	55.50 ✓
15	FRONT BUMPER REINFORCEMENT ? <i>X SMC</i>	1	P971-805-241-E -		\$	1,080.80
16	FRONT BUMPER SPONGE ? <i>X SMC</i>	1	P971-807-550- -		\$	82.50
17	SUPPORT LOWER REINFORCEMENT ? <i>X SMC</i>	1	P971-803-821-B -		\$	303.20
18	ADDITIONAL HEADLAMP LH <i>SCA</i>	1	P971-953-041-H -		\$	744.10 ✓
19		0	0		\$	-
20		0	0		\$	-
TOTAL PARTS					\$	7,592.10
LESS 10%					\$	759.21
TOTAL PARTS COST					\$	6,832.89

Labour Description

1	TO REMOVE /INSTALL FRONT BUMPER, LOWER SPOILER & ALL DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560	\$	3,900.00 ✓
2	TO RESPRAY FRONT BUMPER .	1360	\$	1,850.00 ✓
3	TO SUPPLY FRONT LICENCE PLATE WITH CASING	NETT	\$	70.00 ✓

	TRANSFER THE FRONT BUMPER SENSORS.	150	\$ 500.00
	TO TRANSFER THE FRONT CAMERA	150	\$ 350.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	180	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	NETT	\$ 600.00
8	SUNDRIES.	NETT	\$ 20 50.00

TOTAL LABOUR	\$ -	\$ 7,570.00
TOTAL PARTS	\$ -	\$ 6,832.89
TOTAL	\$ -	\$ 14,402.89
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
3 days
18/12/2020 @ 1515
Resay before print