

Date: 14.07.2020
Vehicle No: SKX4997R
Model: HONDA VEZEL 1.5X CVT
Chassis: RU11104883-2015
Reg.Year: 2015

Third Party Insurer: AIG
Third Party Veh No: SJZ1437L
Date of Accident: 11.07.2020

Not Authorised

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR WHEEL ARCH EXTENTION COVER RH	1	<i>Not in</i>	\$192.00 ✓
2	REAR ALLOY RIM RH	1	500SN <i>Not</i>	\$1,521.00 ✓
3	REAR SIDE BUMPER RH	1		REPAIR
SUB TOTAL				\$1,713.00
LESS 20%				-\$342.60
PARTS TOTAL				\$1,370.40

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR TYRE TUBE VALVE RH	1	<i>Not</i>	\$12.00 ✓
S/N TOTAL				\$12.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST REAR ACCIDENT AREAS & ETC. \$250.00 *80*

LABOUR CHARGES TO REMOVE, REFIX, REPLACE REAR ALLOY RIM RH & ETC. \$80.00 *20*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC. \$200.00 *100*

LABOUR TOTAL \$530.00

TingAn **TOTAL** \$1,912.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 / Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 / Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 / Fax: (+65) 6452 9223

