



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 14.12.2020
Emailed : 20.01.2021, 5pm
Date Survey : 12.01.2021

VEHICLE NO : SMQ 1067 H
MODEL : MIT OUTLANDER 2.0
WIP : 60763

Table with 2 columns: Description and Amount. Rows include Material (\$936.32), Labour (\$2,395.00), Sub-Total (\$3,331.32), Less Excess (\$300.00), Total (\$3,031.32), GST 7% (\$212.19), Grand Total (\$3,243.51), and Finalise By/Date (LOI / 20/01/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[ ] SURVEYOR'S REPORT REQUIRED

[ ] REPAIR TOOK WORKING DAYS + 0 Days ( 0 ) Weekends
+ 0 Days ( 0 ) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[ ] TP claim

[ ] Claim GIA / LTA fee

[ ] Claim Loss of Use / Rental

[ ] Claim Medical Fee / Others

[ ] Third Party Report



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892  12/01/2021	Cust No/Name	/CHAN HEN FUI
	Reg No/Reg Date	SMQ1067H / 30/10/2019
	Date In/Mileage	12/01/2021/ 9724
	Chassis/Package	GF7W0601257 /DC17P
	Engine No	4J11AR9005
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	COO QUARTZ BROWN ME/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	19/01/2021/ 17:39	BLC	260 / AiTing	60763

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REPAIR TAILGATE, REAR FENDER RH, SKID PLATE				✓ 900.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				✓ 60.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, TAIGLATE, REAR FENDER RH, SKID PLAT				✓ 1225.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				✓ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				✓ 120.00
M SUNDRY C&C LOGO				✓ 40.00
M SUNDRY Sundry				✓ 20.00
X EXC EXCESS FOR OWN DAMAGE CLAIM				-300.00
X FACE,RR BUMPER	1.00	✓ 807.00	23.00	621.39
X BRKT,R/BMPR FACE SIDE,RH	1.00	✓ 12.00	23.00	9.24
X MOULDING,RR BUMPER,RH	1.00	? 106.00	23.00	81.62
X MARK,OUTLANDER	1.00	✓ 95.00	23.00	73.15
X DECAL,MIVEC	1.00	36.00	23.00	27.72
X MOULDING,RR WHEEL ARCH,RH	1.00	160.00	23.00	123.20
Z TEXT AIG OD CLAIM DOA : 14.12.20 SURVEYOR STEVE LKK 12.01.2021 POLICY NO: 1900234418, REPAIR 04 DAYS				

*Guarantee Your Warranty, Maintain with Cycle & Carriage!*

Parts	936.32		Nett	3,031.32
Labour	2,335.00	7% GST on	3031.32	212.19
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00			
Sundry/Others	-240.00			
<b>Total(w/o GST)</b>	<b>3,031.32</b>		<b>Total Payable</b>	<b>3,243.51</b>

This is not an official tax invoice.  
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMQ 1067 H

	<u>Material</u>	<u>Cost (\$)</u>
1	Decal, Mivec	36.00 / nec
2	Moulding, RR wheel arch, RH	160.00 / nec
		-----
		196.00
	Less 23%	45.08
		-----
	Total Materials	150.92
	7% GST	10.56
	<b>Grand total</b>	<b><u>\$ 161.48</u></b>

Thank You.

Yours faithfully  
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LOI AI TING  
SENIOR OFFICER - ADMIN  
DID : 6568 4556 / 4501  
FAX : 6567 5258 / 6565 1240

SM12106FH

After we MUT-3, we went to Base all the sound  
to Job Done.

2021.01.18

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20091-00
V.C.I. Version	B178
Vehicle Information	DBA-GF7W 2019MY

All DTCs

2021.01.18

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCs	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCs	
AT/CVT/A-MT/TC-SST	CVT_14080300		No DTCs	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCs	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCs	
SRS-AIR BAG	ORC_81047302		No DTCs	
Air Conditioner	AC_80080011		No DTCs	
ETACS	ETACS_83040801		No DTCs	
Meter	MTR_84084001		No DTCs	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000		Non-equipped System or Communication Error	

All DTCs

2021.01.18

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error	