



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Table with 2 main columns: Invoice Name & Address (CHAN HEN FUI, 143 MOULMEIN ROAD, SINGAPORE 308088, Contact No Mobile: 94880309) and Owner Name & Vehicle Info (Cust No/Name: /CHAN HEN FUI, Reg No/Reg Date: SMQ1067H / 30/10/201, Date In/Mileage: / 0, Chassis No: GF7W0601257, Engine No: 4J11AR9005, Make/Model: MIT/19MY OUTLANDER 2.0 MODERN(995), Colour/Trim: COO QUARTZ BROWN ME/ BK BLACK)

Table with 6 columns: Account No (CSM00041), Terms (Cash), Date/Time Printed (15/12/2020/ 17:11), CSE (Bod), Operator (442 / CocoLu), WIP No (60763)

Main items table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like RENEW REAR BUMPER, REPAIR TAILGATE, REAR FENDER RH, SKID PLATE 450 X 2 (900.00), REMOVE & INSTALL PARKING SENSOR (60.00), SPRAY PAINT FOR REAR BUMPER, TAIGLATE, REAR FENDER RH, SKID PLAT 1/2 350 x 3-5 (1750.00), CHECK WIRING & ELECTRICAL SYSTEM (30.00), TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST (120.00), C&C LOGO (40.00), Sundry (20.00), FACE, RR BUMPER (807.00), BRKT, R/BMPR FACE SIDE, RH (12.00), REINFORCEMENT, RR BUMPER, RH (79.00), MOULDING, RR BUMPER, RH (106.00), MARK, OUTLANDER (95.00). Total amount 1225.

Estimate

SURVEYOR NAME: Steve (CLKK)
SURVEYOR SIGNATURE: 12/1/21, 2-30pm
DATE: 00- Not Avl
REMARKS: Excess - ?
P/P
By Bel spy

Summary table with columns: Description, 7% GST on, Total Payable. Includes '4 days' note. Total Payable: 4,300.33

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimate codes quoted are, excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.