

ASS. REC. BY: Marcus

REF:

CC4/111200/3915/4653

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW8007
Soc lean

at Workshop m/s

of

Insured:

SHA 40528

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

£19k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

3

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1562

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLW8007R

Yr Regn:

22/1/09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

CA/

Make:

Toyota Rush

c.c

1495

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

145146

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

J200E0023972

Gen. Cond:

Good / Fair / Poor / Burnt

Steering:

In order / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

3/1/20

D.O.I.

16/1/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

CR until 21-1-2024 LTA 8073

18/1/20 L/S £1500 confirmed with insurer

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

REPAIRING OF
MOTOR VEHICLES,
PANEL BEATING,
WELDING, SPRAYING,
INSURANCE AGENT,
CLAIMS
DEALING IN 2ND
HAND VEHICLE.

速良摩多 SOC LEON MOTOR WORKS

AUTOBAY @ KAKI BUKIT
1 Kaki Bukit Ave 6, Blk D, #01-91, Singapore 417883
Tel: 6747 7858, 6747 2343 Fax: 6742 0012
E-mail: slmoi@singnet.com.sg
Reg No. 206639/00K

修理汽車貨車兼
打嗎甲燒奸噴漆
代理保險：車禍
賠償及買賣汽車

Alvin Jasper

MDM LEE BEE HONG

DATE : 15/12/2020

DOA : 09/12/2020

ESTIMATE REPAIR FOR SLW 8007 R (TOYOTA RUSH)

	Description	List Price	
1 pc	Front bumper (with foglight cover)	\$ 1,180.00	✓ 981.10
1 pc	Bumper side retainer (rh)	\$ 198.00	X
10 pcs / set	Bumper clips @\$6.00	\$ 60.00	✓ 50
1 pc	Bumper reinforcement	\$ 680.00	✓ 595.10
		\$ 2,118.00	
	Less : 25%	\$ (529.50)	
		\$ 1,588.50	
	Special Nett Items		
	Labour charges for knocking & replacing parts.	\$ 300.00	280
	Spraypainting	\$ 400.00	380
	TOTAL :	\$ 2,288.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

not Acknowledged
Alvin Jasper
2/3 ~~1500~~ 1500
3 days
Take photo after repair

P-1626.2
252
12/19.65
1879.65
1503.7