



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0981/2020/NS
DATE : 15-Dec-20
WIP : 62751

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.
YOUR INSURED VEH NO : SMU 4176 K

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MS HUANG XIAOYUN
ADDRESS : 30 RICHARDS AVENUE
SINGAPORE 544947
TELEPHONE : HP +65 93886903
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900170861
VEHICLE NO : **SMQ 8866 Y**
MODEL CODE : AUDI A5 SPORTSBACK 2.0 TFS
MODEL YEAR : 27/9/2019
ENGINE NO : CVK 087333
CHASSIS NO : WAUZZZF57KA074742
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Dec-20
PLACE OF ACCIDENT : UNITED SQUARE 101 THOMSON ROAD


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMQ 8866 Y

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓ 280	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00 1000	
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 2,500.00 1100	
5	TO RENEW LHS FRONT RIM AND CARRY OUT ALIGNMENT.	S/N \$ 280.00 X	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>6,252.00</u>	



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8866 Y

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Dehnd</i>		\$ 2,251.00	✓
2 FRONT BUMPER FIXING PARTS <i>new</i>		\$ 402.00	+
3 FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 70.00	+
4 FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>		\$ 225.00	+
5 FRONT BUMPER AIR GUIDE - LH <i>new</i>		\$ 62.00	+
6 FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>		\$ 468.00	+
7 FRONT BUMPER GUIDE SECTION - LH		\$ 36.00	+
8 FRONT PARKING AID SENSOR - OUTER		\$ 242.00	+
9 FRONT PARKING AID SEAL RING	4	\$ 14.00	+
10 FRONT FENDER - LH <i>Dehnd</i>		\$ 1,048.00	✓
11 FRONT FENDER ATTACHMENT PARTS <i>new</i>		\$ 53.00	+
12 FRONT FENDER CLOSING ELEMENT - LH <i>new</i>		\$ 73.00	+
13 FRONT FENDER BRACKET - LH ?		\$ 35.00	?
14 FRONT FENDER BRACE - LH ?		\$ 117.00	?
15 DEFORMATION ELEMENT BRACKET - LH <i>M</i> S/N		\$ 49.00	+
16 FRONT FENDER TRIM - LH <i>new</i>		\$ 157.00	✓
17 WHEEL HOUSING LINER - LH <i>new</i>		\$ 272.00	+
18 WHEEL HOUSING LINER ATTACHMENT PARTS <i>M</i>		\$ 167.00	+
19 WHEEL SPOILER - LH		\$ 73.00	+
20 WHEEL SDPOILER TRIM - LH <i>new</i>		\$ 35.00	+
SUB TOTAL SPARE PARTS	:	\$ 5,849.00	


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMQ 8866 Y

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 STONE CHIP GUARD - LH <i>new</i>		\$ 50.00	<i>+</i>
22 TOP FENDER LEDGE COVER - UPPER <i>?</i>		\$ 35.00	<i>?</i>
23 TOP FENDER LEDGE COVER - LOWER <i>?</i>		\$ 16.00	<i>?</i>
24 LED HEADLIGHT - LH <i>cut</i>		\$ 7,812.00	<i>✓</i>
25 LIFT CYLINDER - LH <i>new</i>		\$ 196.00	<i>+</i>
26 FRONT ALUMINIUM RIM - LH <i>new</i>		\$ 1,012.00	<i>+</i>
27 SUNDRIES <i>?</i>		\$ 200.00	<i>?</i>
TOTAL SPARE PARTS	:	\$ 15,170.00	
TOTAL LABOUR CHARGES	:	\$ 6,252.00	
GRAND TOTAL	:	\$ 21,422.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *18/12/20*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised , 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT