

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Co Reg No : 1977014690		Owner Name & Vehicle Info	
Invoice Name & Address			
Mr Shanmugavel Rajan Raja Jawahar		Cust No/Name	/Mr Shanmugavel Rajan Raja Jawah
Apt Blk 654 Yishun Avenue 4		Reg No/Reg Date	SFE3383C / 28/02/201
#08-433		Date In/Mileage	/ 0
Singapore 760654		Chassis No	GF7W0401054
Contact No Mobile: 92362883		Engine No	4J11XK6125
		Make/Model	MIT/OUTLANDER 2.0 2WD CVT SPORTS (9
		Colour/Trim	W01 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	14/12/2020/ 14:46	BLC	442 / CocoLu	60678

CSM00041	Cash	14/12/2020/ 14:46	BLU	442 / 000000					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E PNT88000	R	/						450.00	/
REPAIR FRT BUMPER, RENEW FRT FENDER RH								700.00	/
E PNT98000		/						120.00	/
SPRAY PAINT FOR FRT BUMPER, FRT FENDER RH								30.00	/
B WHEELALIGNMENT								30.00	/
To Conduct Computerize Full Wheel Alignment								30.00	/
M SUNDRY								30.00	/
TRANSFER FRT RIGHT RIM								450.00	/
A 54900099								120.00	/
CHECK WIRING & ELECTRICAL SYSTEM								20.00	/
A 54900099								450.00	/
RENEW FRT UNDER CARRIAGE								120.00	/
A 10028901								20.00	/
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST									
USING HI-SCAN PRO TEST									
M SUNDRY									
Sundry									
M FENDER,FR RH					1.00	688.00	00.00	688.00	
M SHAFT AS,FR AXLE DRIVE,RH					1.00	1285.00	00.00	1285.00	
M WHEEL,SPARE TIRE DISC					1.00	1102.00	00.00	1102.00	
M ARM ASSY,FR SUSP,LWR RH					1.00	323.00	00.00	323.00	
M STRUT,FR SUSP,RH					1.00	465.00	00.00	465.00	
M BEARING,FR SUSP STRUT					1.00	32.00	00.00	32.00	
M LINK,FR SUSP STABILIZER					1.00	137.00	00.00	137.00	
M GEAR & LINK ASSY,STEERING					1.00	1211.00	00.00	1211.00	
M END ASSY,TIE ROD					1.00	62.00	00.00	62.00	

Estimate

OO

X

CUT

?

X

X

X

Stere (CLKK)

14/12/20, 3.00pm

4 days

OD- N4 Authnre

EXCISE - ?

112

LKK Auto Consultants hence notify

Stere (LKK)

14/12/20, 3.00pm

4 days

OD- NH Author

EXCISE - 2

p/p

Ry BOL sy

LKK Auto Consultants hence notify
the Repairer of the following:

- Confirm & accepted by** before/after spray painting
- To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

	Nett	7,225.00
7% GST on	7225.00	505.75
	Total Payable	7,730.75

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.