



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08915/LOH YUE THONG Reg No/Reg Date SMJ7059D / 18/03/201 Date In/Mileage / 0 Chassis No KNAF1416MK5025200 Engine No G4FGJH714153 Make/Model KIA/CERATO 1.6 A L S116 Colour/Trim BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	14/12/2020/ 09:54		442 / Cocolu	25707

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, FRT FENDER LH, FRT SUPPORT PENEL, 419 X1 REPAIR FRT DOOR LH, BONNET				800 1600.00
E PNT88000 REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR				? 100.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT DOOR LH, BONNET				700 1400.00
M SUNDRY Sundry				20.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
M COVER-FR BUMPER / BR	1.00	633.00	20.00	506.40
M GRILLE-FRONT BUMPER / CUT	1.00	262.00	20.00	209.60
M LAMP ASSY-DAY RUNNING LIGHT, LH X CUT	1.00	203.00	20.00	162.40
M MOULDING-FRONT BUMPER, LH / CUT	1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER, LH / CUT	1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER, LH / BR	1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY X	1.00	84.00	20.00	67.20
M BRACKET-FR BUMPER UPR SIDE, MTG / BR	1.00	22.00	20.00	17.60
M PANEL-FENDER, LH / BR	1.00	430.00	20.00	344.00
M CARRIER ASSY-FRONT END MODULE ?	1.00	675.00	20.00	540.00
M LAMP ASSY-HEAD, LH / BR	1.00	1040.00	20.00	832.00
M GUARD ASSY-FRONT WHEEL, LH / CR4	1.00	95.00	20.00	76.00
M DUCT ASSY-EXTENSION (Rear) / BR	1.00	115.00	20.00	92.00

Estimate

Steve CLKK)
14/12/20, 10.00am

OD - AM AL

Express - ?

P/P

By Belgy

4 dys

Confirm & accepted by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

* Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

Nett	6,391.60
7% GST on	6391.60
Total Payable	6,839.01

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.