

Reg No : 199405410K ESTIMATE GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name
	Reg No/Reg Date
	Date In/Mileage
	Chassis No
	Engine No
	Make/Model
	Colour/Trim
LCV08915/LOH YUE THONG SMJ7059D / 18/03/201 / 0 KNAF1416MK5025200 G4FGJH714153 KIA/CERATO 1.6 A L S116 BBL HORIZON BLUE / WK SATURN BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	14/12/2020/ 09:54		442 / Cocolu	25707
Description of Goods / Services					Amount
E PNT88000					1600.00
RENEW FRT BUMPER, FRT FENDER LH, FRT SUPPORT PENEL , 470 X 2					
REPAIR FRT DOOR LH, BONNET					100.00
E PNT88000					1400.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR					
E PNT98000					20.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT DOOR LH, BONNET					
M SUNDRY					30.00
Sundry					
A 90000001					120.00
CHECK WIRING & ELECTRICAL SYSTEM					
A 10028901					120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST					
USING HI-SCAN PRO TEST					
B WHEELALIGNMENT					
To Conduct Computerize Full Wheel Alignment					
M COVER-FR BUMPER			1.00	633.00 20.00	506.40
M GRILLE-FRONT BUMPER			1.00	262.00 20.00	209.60
M LAMP ASSY-DAY RUNNING LIGHT, LH			1.00	203.00 20.00	162.40
M MOULDING-FRONT BUMPER, LH			1.00	36.00 20.00	28.80
M LAMP ASSY-SIDE REPEATER, LH			1.00	143.00 20.00	114.40
M AIR DUCT-FR BUMPER, LH			1.00	14.00 20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY			1.00	84.00 20.00	67.20
M BRACKET-FR BUMPER UPR SIDE, MTG			1.00	22.00 20.00	17.60
M PANEL-FENDER, LH			1.00	430.00 20.00	344.00
M CARRIER ASSY-FRONT END MODULE			1.00	675.00 20.00	540.00
M LAMP ASSY-HEAD, LH			1.00	1040.00 20.00	832.00
M GUARD ASSY-FRONT WHEEL, LH			1.00	95.00 20.00	76.00
M DUCT ASSY-EXTENSION (Rear)			1.00	115.00 20.00	92.00

Estimate

Confirm & accepted by

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

By BCL Sy
 4 dys

Nett	6,391.60
7% GST on	6391.60
Total Payable	6,839.01

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.