



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909			Ref: CS/UOI20013930/Ktd3e2	
			Date: 17/03/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SKE 1231L
	Policy No.	DHOM120037321800	Coverage (\$)	0.00
	Claim No.	M12D12361912	Excess (\$)	750.00
	Assign From	JOSEPHINE WONG	Assign Date	16/12/2020
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WDD1173422N646259	Colour	METALLIC BLACK
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/40 R18	DUNLOP	7 mm
	L/H Front Tyre	225/40 R18	DUNLOP	7 mm
	R/H Rear Tyre	225/40 R18	DUNLOP	8 mm
	L/H Rear Tyre	225/40 R18	DUNLOP	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND FRONT WINDSCREEN CRACKED. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	21/11/2019	Inspection Date	16/12/2020
	Survey held at	10 Ang Mo Kio Industrial Park 2A #01-05		
	Repairer	OPTIMA WERKZ PTE LTD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$110,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	