

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJF9324G**
 MODEL : **HONDA STREAM**
 DATE OF ACCIDENT : 14.12.20
 TIME OF ACCIDENT : 15:30HRS

28	REAR FLOOR PANEL COVER BOARD (INNER SUPPORT) <i>new</i>	1	\$ 697.60	\$ 697.60	+
29	REAR TOOLS SPONGE <i>3 All</i>	1	\$ 168.20	\$ 168.20	+
30	REAR JACK COVER GARNISH <i>new</i>	1	\$ 185.00	\$ 185.00	+

2749.90
 2199.92

TOTAL PRICE \$ 8,706.20
 LESS 20% \$ 1,741.24
SUB TOTAL PRICE \$ 6,964.96

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 80.00	\$ 80.00	50
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	30
3	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
4	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	+
5	TAILGATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00	+
6	TAILGATE OUTER GARNISH CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00	20
7	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	30
8	TAILGATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00	30
9	TAILGATE WINDSCREEN SOLAR FILM <i>new</i>	1	\$ 550.00	\$ 550.00	200
10	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	+
11	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
12	REAR JACK COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
13	JACK <i>new</i>	1	\$ 150.00	\$ 150.00	+
14	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	+
15	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	+
16	BICYCLE (G8EA1875) <i>new</i>	1	\$ 6,800.00	\$ 6,800.00	2500
17	BICYCLE (502671001) <i>new</i>	1	\$ 1,200.00	\$ 1,200.00	+
18	BICYCLE BUZZ RACK <i>new</i>	1	\$ 500.00	\$ 500.00	300

~~3160~~ TOTAL \$ 10,770.00
 360

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,400.00	300
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,400.00	400
3	TUFF COAT	\$ 250.00	30
4	WIRING AND BULB CHECK	\$ 180.00	X

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJF9324G**
 MODEL : **HONDA STREAM**
 DATE OF ACCIDENT : 14.12.20
 TIME OF ACCIDENT : 15:30HRS

5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	X
6	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00 50	
7	REAR CHASSIS ALIGNMENT	\$ 250.00	X
8	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
10	CONDUCT WATER LEAKAGE TEST	\$ 180.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

980

TOTAL \$ 4,200.00

ESTIMATE REPORT

TOTAL PARTS COST : \$17,734.96
 TOTAL LABOUR COST : \$4,200.00
 TOTAL REPAIR COST : \$21,934.96

Adrian Lj
l/s 16/12/20
04 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

total: 3539.92
l/s: 2&k.

MICHELLE
 SERVICE ADVISOR
 MICHELLE
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Psychic separate claim