

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance
Date: 15/12/2020
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLF2976Y
CHASSIS NO : NSP1707017543
MAKE / MODEL : Toyota Sienta 1.5 x Auto
DATE OF ACCIDENT : 15/12/2020
YOUR INSURED VEHICLE NUMBER : GBK3730A
MILEAGE : 307862 km

	PARTS DESCRIPTION	QTY	UNIT PRICE	LIST PRICE
1	F/L door / DD	1PC	\$ 1,404.00	\$ 1,404.00
2	F/L door regulator	1PC	\$ 480.50	\$ 480.50
3	F/L door window motor	1PC	\$ 528.30	\$ 528.30
4	R/L door / DD	1PC	\$ 1,404.00	\$ 1,404.00
5	R/L fender / DD	1PC	\$ 1,255.00	\$ 1,255.00
6	R/L fender rubber pad / SCR	1PC	\$ 280.00	\$ 280.00
7	R/L door rubber pad / SCR	1PC	\$ 390.00	\$ 390.00
8	Rear bumper / CR4	1PC	\$ 1,257.83	\$ 1,257.83
LIST TOTAL S\$:				\$ 6,999.63
25.00% DISCOUNT S\$:				\$ 1,749.91
				\$ 5,249.72

SPECIAL NETT				
1	Bumper clips / NEC	1 SET	\$ 80.00	30
2	Body sealant / NEC	1PC	\$ 300.00	80
Special Nett Total S\$:			\$ 380.00	

LABOUR CHARGES				
1	To labour charge for removing F/L door, R/L door, rear bumper out to facilitate replacement of parts. Also repair R/L fender		\$ 1,200.00	/
2	To respray rear bumper, F/L door, R/L door and R/L fender		\$ 1,200.00	1000
3	To remove and install rear tailgate glass		\$ 120.00	X
4	Transfer tailgate mechanism		\$ 100.00	/
5	To configure keyless network security system back to factory specification		\$ 300.00	X
6	To deactivate and activate high voltage hybrid battery as a requirement for safety precautions		\$ 300.00	X

LABOUR TOTAL S\$:	\$ 3,220.00
TOTAL S\$:	\$ 8,849.72
7% GST	\$ 619.48
GRAND TOTAL S\$:	\$ 9,469.20

Tuning Fee \$50

Repair dy - 6 days

For L/S
After primphow

Sim Pmellm

16/12/2020

TP with primphow

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: