

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013951/UPS3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800032345

Claimant
Vehicle No : GBC2546P **Insured Vehicle No :** SJT1909Z

Date of Loss: 14/12/2020 Nature of Claim: TP Claim No: 8542020541SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC2546P		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2116632
Reg. Date:	22/09/2011 (Man. Year: 2011)	Chassis No:	JTFAT35Y40K201679
Colour:	Silver	Odometer:	212808 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Michelin 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,303.80	2,893.42	1,410.38	32.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,150.00	1,510.00	640.00	29.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,453.80	4,403.42	2,050.38	31.77
Approved Total (Overridden) (\$\$)		3,500.00		
(\$\$)	6,453.80	3,500.00	2,953.80	45.77
+ GST 7.00/7.00% (\$\$)	451.77	245.00	206.77	45.77
Nett Amount (\$\$)	6,905.57	3,745.00	3,160.57	45.77
+ Car Rental (6.0 x S\$80.00/day) (\$\$)		480.00		
+ Doc/Search Fee (\$\$)		31.00		
Nett Liability (\$\$)		4,256.00		

INSPECTION

Date of Assignment: 16/12/2020

Date Inspected: 16/12/2020 Inspected At:

Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48/50 Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Badly Dented	853.10 FL	*853.10 FL
2	1		*FRONT PANEL DYNA EMBLEM	Necessary	69.10 FL	*69.10 FL
3	1		*FRONT PANEL TOP GARNISH	Not Necessary	258.90 FL	*- FL
4	1		*FRONT GRILLE	Cracked	475.10 FL	*424.10 FL
5	1		*FRONT GRILLE RUBBER SEAL	Necessary	20.20 FL	*20.20 FL
6	1		*FRONT GRILLE EMBLEM	Necessary	65.20 FL	*65.20 FL
7	1		*FRONT HEAD LAMP LH	Cracked	517.10 FL	*517.10 FL
8	1		*FRONT HEAD LAMP LOWER SEAL LH	Torn	33.90 FL	*33.90 FL
9	1		*FRONT BUMPER	Bent	461.10 FL	*398.60 FL
10	1		*FRONT STEP PANEL GARNISH LH	Not Necessary	246.40 FL	*- FL
11	1		*FRONT AIR CON BLOWER	Cracked	650.40 FL	*650.40 FL
12	1		*FRONT AIR CON HEATER ASSY	Cracked	786.20 FL	*786.20 FL
13	1		*FRONT DOOR LH	Repair	867.50 FL	*- FL
14	1		*FRONT DOOR HINGE LOWER LH	Not Necessary	48.10 FL	*- FL
15	1		*FRONT DOOR LOCK LH	Not Necessary	346.10 FL	*- FL
16	1		*FRONT DOOR STICKER LH	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,728.40	3,847.90
- List Item Discount on L Items 25.00/25.00% (\$)	1,424.60	954.48
Total Parts (\$)	4,303.80	2,893.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	950.00	680.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	30.00
4	TO REMOVE & REPLACE AIR CON BLOWER ,COOLING CORE AND CHARGE GAS	New	280.00	100.00
5	TO SPRAY PAINTING	New	800.00	680.00
Gross Labour Cost (\$\$)			2,150.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >