

Hk Hsiao Tony

not Authorized
16/12/20
1/5 \$ 3500 /
5 days
to the After repair

FOCUS AUTO PTE LTD
NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

M/S : AIG INSURANCE

Estimate No : M001727

Date : 15/12/2020

Veh Reg No : GBC2546P

ATTN : Motor Claim Department

Make/Model : TOYOTA DYNA

Your Ref No: : GBC2546P

Chassis No : JTFAT35Y40K201679

Claim Type : THIRD PARTY

Engine No: 1KD2116632

Accident Date : 14/12/2020

Reg. Date : 22/09/2011

Estimate Repair Cost to Vehicle No : GBC2546P

PAGE:1/2

S/N	Description	Quantity	Unit	Price	Amount
	<u>LIST PRICE</u>			<u>SS</u>	<u>SS</u>
1	Front Panel <i>Red 500</i>	1	PCS	853.10	853.10 ✓
2	Front Panel Emblem <i>'Dyna' emblem rec</i>	1	PCS	69.10	69.10 ✓
3	Front Panel Top Garnish <i>11</i>	1	PCS	258.90	258.90 X
4	Front Grille <i>one 424.10</i>	1	PCS	475.10	475.10 ✓
5	Front Grille Rubber Seal <i>rec</i>	1	PCS	20.20	20.20 ✓
6	Front Grille Emblem <i>rec</i>	1	PCS	65.20	65.20 ✓
7	Front Head Lamp LH <i>cm</i>	1	PCS	517.10	517.10 ✓
8	Front Head Lamp Lower Seal LH <i>11</i>	1	PCS	33.90	33.90 ✓
9	Front Bumper <i>Best 398.60</i>	1	PCS	461.10	461.10 ✓
10	Front Step Panel Garnish LH <i>11</i>	1	PCS	246.40	246.40 X
11	Front Air Con Blower <i>cm</i>	1	PCS	650.40	650.40 ✓
12	Front Air Con <i>heater</i> Cooling Core Assy <i>heater assy</i>	1 <i>cm</i>	PCS	786.20	786.20 ✓
13	Front Door LH <i>11</i>	1	PCS	867.50	867.50 X
14	Front Door Hinge Lower LH <i>11</i>	1	PCS	48.10	48.10 X
15	Front Door Lock LH <i>11</i>	1	PCS	346.10	346.10 X
TOTAL				5698.40	5698.40
DISCOUNT 25%				4273.80	4273.80

SPECIAL NET

16	Front Door Sticker LH <i>rec</i>	1	PCS	30.00	30.00 ✓
TOTAL				30.00	

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

M/S : AIG INSURANCE

Estimate No : M001727

Date: : 15/12/2020

Veh Reg No : GBC2546P

Make/Model : TOYOTA DYNA

Chassis No : JTFAT35Y40K201679

Engine No: 1KD2116632

Reg. Date : 22/09/2011

ATTN : Motor Claim Department

Your Ref No: : GBC2546P

Claim Type : THIRD PARTY

Accident Date : 14/12/2020

Estimate Repair Cost to Vehicle No : GBC2546P

PAGE:2/2

S/N	Description	Quantity	Unit	Price	Amount
LABOUR CHARGES				S\$	S\$
17	Panel Beating				950.00 680
18	Check Wiring				60.00 20
19	Rust Proofing				60.00 30
20	To Remove & Replace Air Con Blower, Cooling Core and Charge Gas				280.00 100
21	To Spray Painting				800.00 680
TOTAL					2150.00
OVERALL TOTAL					6453.80

FOR FOCUS AUTO PTE LTD



AUTHORISE SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7- 3817.90
25%
2863.42
4403.42
20%
3522