

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0979/2020/NS
DATE : 15-Dec-20
WIP : 62783

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR YANG XIAO
ADDRESS : 9 JURONG LAKE LINK
#09-35
SINGAPORE 648164
TELEPHONE : HP +65 96533955
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900097924-01
VEHICLE NO : **SML 2722 U**
MODEL CODE : AUDI Q2 1.0 TFSI STRONIC
MODEL YEAR : 13/5/2019
ENGINE NO : CHZ C29865
CHASSIS NO : WAUZZZGA3KA054581
MILEAGE : 16145KM
DATE IN : 14-Dec-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Dec-20
PLACE OF ACCIDENT : BUS STOP OPPOSITE LAKESIDE STATION


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 2722 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1500
5	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER.	\$ 4,500.00	1800 3 x 550 = 1650 Mirror : 150 1800
6	TO RENEW LHS FRONT RIM AND CARRY OUT ALIGNMENT.	S/N \$ 280.00	✓
7	TO TOW VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,412.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 2722 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>Repair</i>	\$	1,854.00	<i>x</i>
2 FRONT BUMPER FIXING PARTS <i>new</i>	\$	343.00	<i>+</i>
3 FRONT BUMPER ADAPTER - LH <i>new</i>	\$	35.00	<i>+</i>
4 FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$	167.00	<i>+</i>
5 FRONT BUMPER END CAP - LH <i>new</i>	\$	34.00	<i>+</i>
6 HEADLIGHT MOUNTING - LH <i>new</i>	\$	117.00	<i>+</i>
7 LED HEADLIGHT - LH <i>new</i>	\$	4,859.00	<i>+</i>
8 LIFT CYLINDER - LH <i>new</i>	\$	141.00	<i>+</i>
9 FRONT FENDER - LH <i>Dented</i>	\$	1,134.00	<i>✓</i>
10 FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$	40.00	<i>+</i>
11 FRONT FENDER BRACKET - OUTER <i>?</i>	\$	16.00	<i>?</i>
12 FRONT FENDER BRACKET - CENTRE <i>?</i>	\$	47.00	<i>?</i>
13 FRONT FENDER BRACKET - INNER <i>?</i>	\$	16.00	<i>?</i>
14 FRONT FENDER BRACE - LH <i>?</i>	\$	37.00	<i>?</i>
15 FRONT FENDER CLOSING ELEMENT - LH <i>?</i>	\$	33.00	<i>?</i>
16 WHEEL HOUSING LINER - LH <i>new</i>	\$	194.00	<i>+</i>
17 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	57.00	<i>+</i>
18 FRONT WHEEL COVER - LH/RH <i>LH out, RH 2</i>	\$	636.00	<i>✓</i>
19 FRONT DOOR - LH <i>Dented</i>	\$	2,499.00	<i>✓</i>
20 FRONT DOOR ATTACHMENT PARTS <i>new</i>	\$	93.00	<i>+</i>
SUB TOTAL SPARE PARTS	:	\$	12,352.00


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 2722 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT DOOR CATCH ?	\$	119.00 ?	
22 FRONT DOOR COVER - LH <i>nee</i>	\$	254.00 ✓	
23 EXTERIOR MIRROR MOUNTING - LH <i>could</i>	\$	1,013.00 ✓	
24 MIRROR CAP - LH <i>could</i>	\$	167.00 ✓	
25 MIRROR GLASS - LH <i>shattered</i>	\$	217.00 ✓	
26 FRONT ALUMINIUM RIM - LH <i>cut</i>	\$	568.00 ✓	
27 SUNDRIES ?	\$	200.00 ?	
TOTAL SPARE PARTS	:	\$ 14,890.00	
TOTAL LABOUR CHARGES	:	\$ 9,412.00	
GRAND TOTAL	:	\$ 24,302.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

Front LH Door Glass cut -

Front LH Door Glass Mounting cut -

Rear LH Wheel Arc Trim cut ✓



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian L
16/12/20

SURVEYED DATE

:

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 06 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT