

ASS. REC. BY:

REF:

CC31A620039521A#3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SML27224

Yr Regn:

2019, May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi Q2

C.C.

999

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

16145

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU322GA3KA054581

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

215/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

16/12/20

Survey held at

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AL6

Part by Part \$13,472.24, 8days
(Red: 1679376 : 55%)

mv: 105K.

PV: 49.7K.

Nett: 55.3K.

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

8

1)

☐

Final Report

Resurvey No. of Trip:

-

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format:

Lump Sum / B.E.C

13472.24



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0979/2020/NS
DATE : 15-Dec-20
WIP : 62783

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR YANG XIAO
ADDRESS : 9 JURONG LAKE LINK
#09-35
SINGAPORE 648164
TELEPHONE : HP +65 96533955
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900097924-01
VEHICLE NO : **SML 2722 U**
MODEL CODE : AUDI Q2 1.0 TFSI STRONIC
MODEL YEAR : 13/5/2019
ENGINE NO : CHZ C29865
CHASSIS NO : WAUZZZGA3KA054581
MILEAGE : 16145KM
DATE IN : 14-Dec-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Dec-20
PLACE OF ACCIDENT : BUS STOP OPPOSITE LAKESIDE STATION



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 2722 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	X
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	✓
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1500 ✓
5	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER.	\$ 4,500.00	1800 ✓ 3 x 550 = 1650 Mirror : 150 <u>1800</u>
6	TO RENEW LHS FRONT RIM AND CARRY OUT ALIGNMENT.	S/N \$ 280.00	✓
7	TO TOW VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	X
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 9,412.00	



PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 2722 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES S/NETT	REMARKS
1 FRONT BUMPER <i>Repair</i>	\$	1,854.00	X
2 FRONT BUMPER FIXING PARTS <i>new</i>	\$	343.00	+
3 FRONT BUMPER ADAPTER - LH <i>new</i>	\$	35.00	+
4 FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$	167.00	+
5 FRONT BUMPER END CAP - LH <i>new</i>	\$	34.00	+
6 HEADLIGHT MOUNTING - LH <i>new</i>	\$	117.00	+
7 LED HEADLIGHT - LH <i>new</i>	\$	4,859.00	+
8 LIFT CYLINDER - LH <i>new</i>	\$	141.00	+
9 FRONT FENDER - LH <i>Dented</i>	\$	1,134.00	✓ 907.20
10 FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$	40.00	+
11 FRONT FENDER BRACKET - OUTER <i>Not new</i>	\$	16.00	? X
12 FRONT FENDER BRACKET - CENTRE <i>Not new</i>	\$	47.00	? X
13 FRONT FENDER BRACKET - INNER <i>Not new</i>	\$	16.00	? X
14 FRONT FENDER BRACE - LH <i>Not new</i>	\$	37.00	? X
15 FRONT FENDER CLOSING ELEMENT - LH <i>Not new</i>	\$	33.00	? X
16 WHEEL HOUSING LINER - LH <i>new</i>	\$	194.00	+
17 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	\$	57.00	+
18 FRONT WHEEL COVER - LH/RH <i>LH out, RH new 2</i>	\$	636.00	✓ 508.80
19 FRONT DOOR - LH <i>Dented</i>	\$	2,499.00	✓ 1999.20
20 FRONT DOOR ATTACHMENT PARTS <i>new</i>	\$	93.00	+ X
SUB TOTAL SPARE PARTS	:	\$ 12,352.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 2722 U

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 FRONT DOOR CATCH <i>Damaged.</i>	\$	119.00	? <i>94.80</i>
22 FRONT DOOR COVER - LH <i>New</i>	\$	254.00	✓ <i>202.80</i>
23 EXTERIOR MIRROR MOUNTING - LH <i>cracked</i>	\$	1,013.00	✓ <i>810.40</i>
24 MIRROR CAP - LH <i>cracked</i>	\$	167.00	✓ <i>133.20</i>
25 MIRROR GLASS - LH <i>shattered</i>	\$	217.00	✓ <i>173.20</i>
26 FRONT ALUMINIUM RIM - LH <i>cut</i>	\$	568.00	✓ <i>454.40</i>
27 SUNDRIES ?	\$	200.00	? <i>30.24</i>
TOTAL SPARE PARTS	:	\$ 14,890.00	
TOTAL LABOUR CHARGES	:	\$ 9,412.00	
GRAND TOTAL	:	\$ 24,302.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

Front LH Door Glass. cut -

Front LH Door Glass Mounting cut -

Rear LH Wheel Arc Trim cut ✓

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



NAME : Adnan L
SURVEYED DATE : 16/12/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 06 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hereby notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0979/2020/NS

24-Dec-20

GEORGE

1 of 1

SML 2722 U

AUDI Q2 1.0 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

LABOUR

1	To remove and transfer lhs rear door's multi - lock system multi-lock system and power window devices. Inspect for damages.	S/N S	280.00 ✓
2	To install solar film for lhs front door for lhs front door window glass.	S/N S	400.00 ✓
3	To renew lhs rear door.	S	800.00 500
4	To respray lhs rear door	S	900.00 550

PARTS

1	FRONT DOOR WINDOW-LH <i>cut</i>	S	195.00 ✓	155.60
2	FRONT DOOR WINDOW APERTURE SEAL -LH OUTER <i>cut</i>	S	134.00 ✓	106.80
3	REAR WHEEL COVER - LH <i>cut</i>	S	168.00 ✓	134.40
4	REAR DOOR- LH <i>Dented</i>	S	2,499.00 ✓	1999.20
5	REAR DOOR OUTER SEAL - LH <i>on</i>	S	134.00 ✓	106.80
6	BONDING AGENT <i>Ren</i>	S	47.00 ? X	
7	CLEANING SOLUTION <i>Ren</i>	S	65.00 ? X	
8	REAR DOOR CATCH-LH ?	S	119.00 ? 94.80	
9	REAR DOOR COVER-LH ?	S	223.00 ? 178.40	

GRAND TOTAL

\$ 5,964.00

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
S/S 28/12/20

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0979/2020/NS
DATE	:	15-Dec-20
WIP	:	62783

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian

8 days, 2 PH 2 Sundays

2-Mar-21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR YANG XIAO
ADDRESS	:	9 JURONG LAKE LINK #09-35 SINGAPORE 648164
TELEPHONE	:	HP +65 96533955
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	1900097924-01
VEHICLE NO	:	SML 2722 U
MODEL CODE	:	AUDI Q2 1.0 TFSI STRONIC
MODEL YEAR	:	13/5/2019
ENGINE NO	:	CHZ C29865
CHASSIS NO	:	WAUZZZGA3KA054581
MILEAGE	:	16145KM
DATE IN	:	14-Dec-20
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	13-Dec-20
PLACE OF ACCIDENT	:	BUS STOP OPPOSITE LAKESIDE STATION

PREMIUM AUTOMOBILES



100 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SML 2722 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 280.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	
3	TO REMOVE AND TRANSFER LHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 280.00	\$ 280.00
4	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, LHS FRONT DOOR AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	\$ 1,500.00
5	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS WING MIRROR COVER.	\$ 4,500.00	\$ 1,800.00
6	TO RENEW LHS FRONT RIM AND CARRY OUT ALIGNMENT.	S/N \$ 280.00	\$ 280.00
7	TO TOW VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	
7a	Added labour - see attached	\$ 2,380.00	\$ 1,330.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 11,792.00	\$ 5,382.00

PREMIUM AUTOMOBILES



100, BUKIT ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 2722 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT BUMPER		\$ 1,854.00	
2	FRONT BUMPER FIXING PARTS		\$ 343.00	
3	FRONT BUMPER ADAPTER - LH		\$ 35.00	
4	FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 167.00	
5	FRONT BUMPER END CAP - LH		\$ 34.00	
6	HEADLIGHT MOUNTING - LH		\$ 117.00	
7	LED HEADLIGHT - LH		\$ 4,859.00	
8	LIFT CYLINDER - LH		\$ 141.00	
9	FRONT FENDER - LH		\$ 1,134.00	\$ 907.20
10	FRONT FENDER ATTACHMENT PARTS		\$ 40.00	
11	FRONT FENDER BRACKET - OUTER		\$ 16.00	
12	FRONT FENDER BRACKET - CENTRE		\$ 47.00	
13	FRONT FENDER BRACKET - INNER		\$ 16.00	
14	FRONT FENDER BRACE - LH		\$ 37.00	
15	FRONT FENDER CLOSING ELEMENT - LH		\$ 33.00	
16	WHEEL HOUSING LINER - LH		\$ 194.00	
17	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 57.00	
18	FRONT WHEEL COVER - LH/RH	2	\$ 636.00	\$ 508.80
19	FRONT DOOR - LH		\$ 2,499.00	\$ 1,999.20
20	FRONT DOOR ATTACHMENT PARTS		\$ 93.00	
SUB TOTAL SPARE PARTS		:	\$ 12,352.00	\$ 3,415.20

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 2722 U

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
		<i>c/f</i>		
21	FRONT DOOR CATCH		\$	3,415.20
22	FRONT DOOR COVER - LH		\$ 119.00	\$ 94.80
23	EXTERIOR MIRROR MOUNTING - LH		\$ 254.00	\$ 202.80
24	MIRROR CAP - LH		\$ 1,013.00	\$ 810.40
25	MIRROR GLASS - LH		\$ 167.00	\$ 133.20
26	FRONT ALUMINIUM RIM - LH		\$ 217.00	\$ 173.20
27	Added parts - see attached		\$ 568.00	\$ 454.40
28	SUNDRIES		\$ 3,584.00	\$ 2,776.00
			\$ 200.00	\$ 30.24
TOTAL SPARE PARTS			\$ 18,474.00	\$ 8,090.24
TOTAL LABOUR CHARGES			\$ 11,792.00	\$ 5,382.00
GRAND TOTAL			\$ 30,266.00	\$ 13,472.24

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-05/02/21



Supplementary Estimate 2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0979/2020/NS 24-Dec-20 GEORGE 1 of 1 SML 2722 U AUDI Q2 1.0 TFSI	
Quantity	Description		Unit Price	Amount
LABOUR				
1	To remove and transfer lhs rear door's multi - lock system multi-lock system and power window devices. Inspect for damages.	S/N	\$ 280.00	\$ 280.00
2	To install solar film for lhs front door for lhs front door window glass.	S/N	\$ 400.00	NA - KS 26FEB
3	To renew lhs rear door.		\$ 800.00	\$ 500.00
4	To respray lhs rear door		\$ 900.00	\$ 550.00
			\$ 2,380.00	\$ 1,330.00
PARTS				
1	FRONT DOOR WINDOW-LH		\$ 195.00	\$ 155.60
2	FRONT DOOR WINDOW APERTURE SEAL -LH OUTER		\$ 134.00	\$ 106.80
3	REAR WHEEL COVER - LH		\$ 168.00	\$ 134.40
4	REAR DOOR- LH		\$ 2,499.00	\$ 1,999.20
5	REAR DOOR OUTER SEAL - LH		\$ 134.00	\$ 106.80
6	BONDING AGENT		\$ 47.00	
7	CLEANING SOLUTION		\$ 65.00	
8	REAR DOOR CATCH-LH		\$ 119.00	\$ 94.80
9	REAR DOOR COVER-LH		\$ 223.00	\$ 178.40
		MATERIALS	\$ 3,584.00	\$ 2,776.00
		LABOUR	\$ 2,380.00	\$ 1,330.00
	GRAND TOTAL		\$ 8,344.00	\$ 4,106.00

For Premium Automobiles Pte Ltd

 Authorised Signature