

Co. Reg No. 201632730M



QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)		SURVEYOR ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>					
1	Front Bumper			1025.00	del	
2	Front Bumper Side Retainer @ \$108.3			216.60	LH-Ret, RH X un	
1	Front Headlamp LHS @ \$3611			3611.00	cut	
1	Front Headlamp panel LHS @ \$165.50			165.50	X	
1	Front Bumper Fog Lamp Garnish LHS @ \$115.5			115.50	X	
1	Front Bumper Logo			120.00	X	
1	Front bumper Lower grille			410.00	X	
1	Front Fender LHS @ \$510.20			510.20	bl	
1	Front Fender Inner Shield LHS @ \$133.90			133.90	X un	
1	Front Fender 'Hybrid' Emblem			98.00	del	
1	Front LHS Knuckle arm (Hub Assy)			549.40	X	
1	Front LHS Wheel bearing			215.50	X	
1	Front LHS Drive shaft			750.00	X	
				7920.60		0.00
		less	25%	1980.15	25%	0.00
				5940.45		0.00
	<u>SPECIAL NETT ITEMS</u>					
1 set	Front Bumper clips			60.00	30 del	
1	LHS Front sports rim			980.00	cut 350.	
1 set	Front LHS fender inner shield clips			60.00	X un.	
	TOTAL PARTS			7040.45		0.00

ECO Automobile Claims & Repair Pte Ltd

15 Kaki Bukit Road 4 #01-53

Bartley Biz Centre S417808

T: 6384 7515

E: ecoautoclaims@gmail.com

Co. Reg No. 201632730M

**Page No. 2**

Vehicle No. SMS2760Y Toyota Noah DOA 15/12/20

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	400
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	400
3	To perform anti-rust treatment on affected areas	240.00	30
	<i>Tan Kah 47495749/67418434 WP 16/12/20 @ 245 = 3 days bump sum Respray after repair Tan Kah 1/11/2018</i>		
	Labour Total :	2840.00	0.00
	TOTAL (PARTS & LABOUR):	9880.45	0.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: